

<u>Close-up:</u> Spill due to pinhole from inward dent on Cawthorne Channel Well 29T flowline at Mbiama. Picture taken during Joint Investigation of 16th August, 2011.