JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: (Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties) A. GENERAL INFORMATION: 2. Type of incident* OIL SPILL 1. Spill incident Number: 1078673 3. Name of Location 28" NKPOKU - BOMY PIPELINE 4. Name of nearest community G10 5. State: RIVERS 6. LGA TA 7. Type of Production facility/Installation OIL PRELIME 8. Asset owner/District PRELIME **B. INCIDENT INFORMATION:** a. Date of incident: 28TR NOVEMBER 2013 9. Details of incident 11:30 Hours b. Start date/time of investigation: 277 NOVEMBER 2013! c. Investigation End date: 27 NOIEMBER Delia Avestigation duration, days: 1 DAY d. Description of spill point environment Coose soil Direcently excavated area ☐Firmed soil Exposed pipe surface **□**Swampy ☐Under water Drill Rig ☐ Well Platform (on Water) e. Description of leak point (tick as applicable); ☐ Tear (Hack saw cut Drilled hole ☐Inward dent. ☐ Well head tampering Complete Rupture ☐Failed Weld-on illegal hot tap valve, ☐Failed Clamp Missing Pipeline/Flowline Third party tampering with Clamp Crude oil theft (illegal bunkering) point, Third party tampering with flange, Third party tampering with valve setting, ☐ Surge vessel overflow, ☐Saver-pit over flow, Corrosion ☐Flare System/Bund wall failure ☐Accidental party Bulging Outward Cold vent Com unit failure ☐ Valve Failure equipment impact Others (specify) Relief valve failure f. Incident caused by: Third party interference (Sabotage♥, crude theft□; Line theft□; Accidental 3rd party damage□) Others (including Mystery spills) Operational MINNA (MID-BELT. g. Spill point coordinates Measuring unit Northing:

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: 0354

C. RISK ASSE	SSMENT					
10.	Type of environment	nt:				
Lanc	i 🗖 Swamp	□ water	□ Sea	asonal swamp	Shoreline/Wa	aterfront
i.	Type of environmen	t to which oil has	spread:			
\(\sum_{\text{Lance}}\)	i 🗆 Swamp	Water	□Riv	ver (identify)	···	
ii.	Weather condition					
□Rain 11. Distance	Sunny from the nearest sen	□Dry sitive habitat	□Wet	Windy	□Hot	□ccol
□ Drin □ Buil □ Farn □ Fish □ Fish	ernment reserved and king water source of tup area nlands Farm/Pond WITC ing net ers (specify).	I designated prote IDN€ Si FIN VICA	ected area EEM MITY	[m,] [m,] [m,] [m,] [m,]		
12. Contains	nent measures put in	place;				
□Been □Othe		⊠ byke	□Na	tural depression	D rit	
13. Any pict	ures or video coverag	ge?		[N]		
14. Was ther	e any disruption to th	e investigation?		[Y] [V]	/	
If yes give brief de	escription:	e e e e e e e e e e e e e e e e e e e				
	OT	+	P	PLI	CA	BLE
D. TYPE/NUMB	ERS OF PROPER	ΓΙΕS, IF ANY, F	OUND WIT	HIN THE ARE	A OF SPRE	AD OF OIL
15. Structure	es / Properties				-	

S/N	Type of Structures	Description	Size	Number	Comments
				AOSA	AT IMPA
	TADME	Mile	714	MACH	OF MARC
	7	-	-		

16. Crops/Economic Trees

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: 0354

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
1 MOHAN BAMBOO			 		MARTED BY CURSE OIL
					- CURSE OIL

17. Fish/Nets/Ponds


S/N Fish/Nets/Ponds	Description	Quantity/Size	Comments
NONE	WITHIN A	REA OF	IMPACT

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
 	NONE	WITHIN	AREA (FIMPACT
<u> </u>				

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

IN THE LEGIC REPORT, OVERVIEW SKEICH OF THE SILE SHOULD BE EDDED AT GIO SHOWING SUCH SECTION OF 28 NK POKY - BOMY PIPELINE AT GIO SHOWING NOS. BOLT AND NUT REMOVED FROM OLD CLAMP. (THIRD PARTY TAMPERING WITH CLAMP)



F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078 673 JIV report S/N: 0354

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

MINNA MIO-BELT

			AMMA MI	ひーろも	J
S/N	Northing	METERS	MINNA WI	Easting	NETERS
	_	<u>-</u>			
<u> </u>	·				
	•				
-	1				
	 				
					<u> </u>
					
	<u> </u>				45/
				\)/
				15/	<u>/</u>
	Į			9/	
 -			135/	/ 	
			. /	İ	
			<u> 25</u> /	 	
-		()			
			<u></u>		
		\ ^{\\} /			
	-	7		!	
		1/			
<u> </u>					
	10/				-
	6/			 	· ·
	1//			 	
	/			<u></u>	
	-	· · ·			 -
					· · · · · · · · · · · · · · · · · · ·

G. INCIDENT INFORMATION:

20. Impacted Area Details

•	Total calculated area of impact	0.72-119	
•	Impact within SPDC R.O.W	YES	
•	Impact outside SPDC R.O.W	YES	

21. Volume of oil recovered before completion of JIV (Vrect):

MINNA (MID-BELT)-1078673


NAME		NORTH	REMARKS
SP	530227.687	78544.387	SPILL POINT
126	530237.73	78544.477	
127	530243.882	78538.323	FREE PHASE CRUDE OIL IMPACT
128	530234.626	78532.196	FREE PHASE CRUDE OIL IMPACT
129	530228.462	78532.207	FREE PHASE CRUDE OIL IMPACT
130	530222.304	78535.29	FREE PHASE CRUDE OIL IMPACT
131	530222.298	78532.218	LIGHT IMPACT
132	530228.49	78547.566	LIGHT IMPACT
133	530234.67	78556.77	LIGHT IMPACT
134	530219.267	78559.869	LIGHT IMPACT
135	530209.982	78538.384	LIGHT IMPACT
136	530200.726	78532.258	LIGHT IMPACT
137	530166.747	78489.316	LIGHT IMPACT
138	530172.894	78480.09	LIGHT IMPACT
139	530179.075	78489.293	LIGHT IMPACT
140	530169.812	78480.095	LIGHT IMPACT
141	530237.735	78547.549	LIGHT IMPACT
142	530246.975	78544.46	LIGHT IMPACT
143	530064.689	78292.913	LIGHT IMPACT
144	530058.531	78295.996	LIGHT IMPACT
145	530067.787	78302.123	LIGHT IMPACT
146	530012.113	78191.643	LIGHT IMPACT
142a	530244.29	78545.2	CONTAINMENT PITS 1
142b	530247.05	78547.2	CONTAINMENT PITS 1
142c	530248.95	78544.98	CONTAINMENT PITS 1
142d	530246.52	78543.07	CONTAINMENT PITS 1
143a	530238.26	78549.85	CONTAINMENT PITS 2
143b	530240.38	78547.73	CONTAINMENT PITS 2
143c	530236.46	78545.2	CONTAINMENT PITS 2
143d	530234.56	78547.09	CONTAINMENT PITS 2
147	530228.42	78563.27	LIGHT IMPACT
148	530192.19	78477.91	LIGHT IMPACT
149	530155.72	78412.32	LIGHT IMPACT
150	530118.42	78361.52	LIGHT IMPACT
151	530062.06	78320.25	LIGHT IMPACT
152	530019.2	78260.72	LIGHT IMPACT
153	530003.32	78221.82	LIGHT IMPACT
154	529996.97	78146.42	LIGHT IMPACT
155	530012.06	78145.62	LIGHT IMPACT
156	530110.22	78327.13	LIGHT IMPACT
157	530144.08	78380.04	LIGHT IMPACT
158	530177.42	78436.14	LIGHT IMPACT
159	530211.29	78482.17	LIGHT IMPACT
160	530191.71	78488.52	LIGHT IMPACT
161	530186.95	78494.35	LIGHT IMPACT

	Receive and Vised NVL	Barrels
22 Commutatio	on of estimated residual volume on site	
	n of estimated volume of pool of free phase oil (on land or confined water bod	y).
ii.	Average Depth (m) of pool of free phase oil 0.000 m	
iii.	Emulsification factor:	
iv.	Estimated Volume of tool of ite place off	barr
	22.64	
	n of estimated volume of infiltrated oil in the soil (V_{inf}). mated Volume of infiltrated oil at spill point (V inf a)	
i.	Area* (m²) of soil covered by the oil:	j.
ii.	Average Depth (m) above leaking facility i.e. pipeline/flowline: 0.5 m	ie i
iii.	Soil type: SAND (MEDIUM) P. (effective porosity of the soil). 257	<u>o</u> _
, v.	Cause of spill: INTERFERENCEVI. Oil type: BONNY LIGHT	
vii.	Oil Residence time on site, day: 1 DAY	
viii.	Average depth of infiltration below leaking facility i.e. pipeline/flowline:	<u>5m</u>
ix.	Estimated depth of infiltration around spill point:	-
	CERTIFICATION OF THE COMMISSION OF THE 2-26	bai
2. Esti	mated Volume of infiltrated oil at second spill point [if applicable] (Vinf b)	
i.	Area* (m²) of so covered by the foil:	
ii.	Average Depth (iii) wove leaking facility i.e. pipeline/flowline:	
iii.	Soil type: iv. P _e (effective porosity of the soil)	
V.	Cause of spill: vi. Oil type:	
vii.	Oil Residence time on site day:	
viii.	Average depth of infiltration below leaking facility (c. dibeline/flowline:	
íx.	Estimated depth of infiltration around spill point:	
	Nu Nu	barrels
3. E	ated Volume of infiltrated oil outside immediate spill point(s) region (Vinf c)	
	Area (m2) of soil covered by the oil:	
i. ii.	Area (m²) of the pool of free phase oil in touch with soil:	
u. iii.	Average Depth (m) below ground surface of infiltration of oil: 0.5m	
m. iv.	Soil type: SAND MEDIUM	
1v. V.	P _e (effective porosity of the soil). 25%	
₩,•		ь
	VI. Estimated Volume of Intillified oil At 18	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: 0354

ii. Table of average depth of oil on water based on coloration (

**Spill Factors from USCG FOG (2000 . Edition)



24. Calculation of evaporated volume:

i. Estimated Volume available for evaporation within surface area. 49.54 BARRELS 72.

ii. E-Factor: 25 /

iii.

Estimated Volume of evaporated oil Vote 24.06	Barrels
---	---------

Evaporation Factors (E-Factor) for SPDC Crude oil						
Oil Type	Days on site	Bonny Light	Bonny Medium			
Oil Residence time	< 1 day	10%	5%			
	1-7 days	25%	15%			
	> 7 days	40%	25%			



Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m³ to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than I bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

26. GENERAL STATUS OF THE SITE

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: 0354

B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the <u>02/12</u> /2013 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:

 ✓
- State Ministry of Environment [SME]: S
- Nigeria Police Force [NPF]: □
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

28. Appendix 1: Overview sketch of the site

Location :	<u> </u>	
		, •••"
· ·		• ·
1		
	,	•
·		•
	<u> </u>	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1078673 JIV report S/N: 0354

