ar.			95 JIV report S/N: 00684	
(Note:	As practicable as possible the JIT	report is to be signed in the	field by all the participating parties)	
A. GE	ENERAL INFORMATION:			
			of incident* OIL SPILL	
3. Nat	ne of Location 28" Nkyok	4 - BOMY PI	yeline	
4. Naı	ne of nearest community $R - D$	ERE 5. State: Ki	UERS 6. LGA GOKANIA	
7. Typ	oe of Production facility/Installation	OIL PIPELINE 8. A	Asset owner/District PIPELINE	
B. IN	CIDENT INFORMATION:			
ı		44 GUIT, 20 Actual inve	1/4 / 13° 24 PA9 stigation duration, days: Tw/o(2) 1)A7	
I	d. Description of spill point enviro	·		
	Firmed soil	Loose soil	Recently excavated area	
	Under water	☐Swampy	Exposed pipe surface	
	☐ Well Platform (on Water)	•	Drill Rig	
A	dditional observations around the s	pill point:	LiDnii Rig	
			LiDnii Rig	
	dditional observations around the s		□ Tear (),	
	e. Description of leak point (tick a	s applicable); □Hack saw cut □Inward dent,	☐ Tear (), ☐ Well head tampering	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap v	s applicable); □Hack saw cut □Inward dent, alve, □Failed Clamp	☐ Tear (), ☐ Well head tampering ☐ Missing Pipeline/Flowline	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap ve	s applicable); Hack saw cut Inward dent, alve, Failed Clamp	☐ Tear (), ☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap verification of the fillegal bunked	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, valve setting,	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange,	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap vor Crude oil theft (illegal bunke Third party tampering with vor Corrosión	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, ralve setting, Saver-pit over flow,	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange, Surge vessel overflow,	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap v. Crude oil theft (illegal bunke Third party tampering with v. Corrosión Bulging Outward	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund w	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange, Surge vessel overflow, vall failure Accidental 3 rd party equipment	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap vor Crude oil theft (illegal bunke Third party tampering with vor Corrosión Bulging Outward impact Valve Faile	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, ralve setting, Saver-pit over flow, Flare System/Bund wure	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange, Surge vessel overflow, vall failure Accidental 3 rd party equipment m unit failure Cold vent	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap v. Crude oil theft (illegal bunke Third party tampering with v. Corrosión Bulging Outward	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund w	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange, Surge vessel overflow, vall failure Accidental 3 rd party equipment m unit failure Cold vent	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap v. Crude oil theft (illegal bunke Drhird party tampering with v. Corrosión Bulging Outward impact Valve Faile Relief valve failure	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund w ure Others (specify)	Tear (), Well head tampering Missing Pipeline/Flowline Third party tampering with Clamp Third party tampering with flange, Surge vessel overflow, vall failure Accidental 3 rd party equipment m unit failure Cold vent	
	e. Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap ver Crude oil theft (illegal bunke Drilled party tampering with ver Corrosión Bulging Outward impact Valve Failed Relief valve failure for Incident caused by:	s applicable); Hack saw cut Inward dent, alve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund w ure Others (specify)	☐ Tear (), ☐ Well head tampering ☐ Missing Pipeline/Flowline ☐ Third party tampering with Clamp ☐ Third party tampering with flange, ☐ Surge vessel overflow, vall failure ☐ Accidental 3 rd party equipment in unit failure ☐ Cold vent ☐ Cold vent ☐ Cold vent ☐ Cold vent	

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

IT INVEST	IGATION R	LI OKT I OKTIN	SIDENT NO.	1200		o.v.opc		0068	84
g. Sp	Measurit Northing:			MINNA	٨٠٠)-BE	<u>니)</u>	-	
~ O h	Northing.				Lasting.				
SP1		76360		Ì	5	325	20 • 01	6	
SP2		76345	. 94		5.	3253	<u>5 · 93</u>		
	-								
	l								
	ASSESSME								
10.		of environment:							
12	Land	□ Swamp	□Water	□Sea	asonal swa	mp 🗆 Sh	oreline/Wa	aterfront	
	i. Type	of environment to	which oil has s	pread:					
Ţ	Z Land	☐Swamp	□water	□Ri	ver (identi	fy)			
	ii. Weatl	er condition							
	Rain stance from	Sunny the nearest sensitiv	□Dry ve habitat	□Wet	□Win	dy	□Hot	□со	ol
	Governme Drinking v Built up at Farmlands Fish Farm Fishing ne Others (sp	rea /Pond t	signated protec	ted area	[N/L [N/L [S [N/L	,m) ,m) ,m) ,m)			
12. Co	ontainment n	neasures put in plac	ce;						
	Booms Others: <u>F</u>	Trench	DDyke DITCH		tural depre		Deit 1166 p	พากษ์	□None
13. Ar	ny pictures of	r video coverage?			(X)	[N]			
		r video coverage? nse/repair initiated	as at the time o	of JIV?	CYT CYT	[N]			
14. F	urther respon	nse/repair initiated			• 1	[N]	5	me,	Rtp
14. F	urther respon	_	1011FR-1		• 1	[N]	<u>s Do</u>	onles	<u> </u>
14. F	urther respon	nse/repair initiated	BY		• 1	[N]	<u>s </u>	onles	<u> </u>

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1235195 JIV report S/N: 00684

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
N	DME XITH	NU A	REA	-07	IMPACT

17. Crops/Economic Trees

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
Monte	1177	ADE	A DF	TMA	PC5
1110/40 1		1110		1/1/	

18. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
A	onle h	1111+121	AREA OF	IMPACI

19. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
A	ont h	timm pr	REA C	FIMPACT

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

POSITION OF 28" NKYOKY - BOMY PIPELINE AT B-DERE SHOWING



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1235195 JIV report S/N: 00684

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted area	boundary Coordinates	(If more,	Print and attac	h as an appendix)
			The second second	Comment of the property

		Minny ()	MID-B=LT)
S/N	Northing		Easting
		76334.83	532536:41
		76334·83 76362·45 76365·63	532536·41 532508·78 532518·15
		76365.63	532518:15
		76344.04	532545.61
	-		
		,	
		<u>/</u>	
	1		

			· • • · · ·		MI I CD.
NT INVESTIGATIO	N REPORT FOR IN	CIDENT NO: 12	<u> 35195</u>	JIV report S/N:	00684
G. INCIDENT IN					
20. Impacted A	rea Details	•			
_		_	0.01 1		
	otal calculated area of	• ——	756	<u> </u>	-
	npact within SPDC R.0		10>		_
	npact outside SPDC R.	*	NO		-
21. Volume of c	oil recovered before		' " .		
		Recovered oil V	· · · · · · · · · · · · · · · · · · ·	D	Barrels
Controlled rec	covery/evacuation fro		impact to envir	ronment:	
	<i>N</i>	Barrels			
<u> </u>					
22. Net Estima	ted Spilled Volume	$V_{Est}(bbls)^* =$			
	110	21 240	RHLI		
No. 2 to the second sec	4 3.	TI DAY	んてし	and the second	
Estimated Reporte	d Volume** Vren(bbl	<u> 46</u>	RARRE	-1 r	
<u> </u>			DAIACK	<u></u>	
*Notes:	ation was done using an exc	al hannel toni fann uttuuks	dan datata da -	ada ada ada a	
 Reported spill 	led volume is an estimate				
Write other relevan	it notes taken into considera	tion for estimating the spi	lled in the box below	<i>':</i>	
•					
See	MITAG	HED			
	• •	•			
Calculation of the various	tive estimated volume is to b			717 /	
Conversion of m' to barre	els is Volume (m3) x 6.29; 🤚	e uone on site as jar as pi *Round up estimated volu rounded up to the next wh	ume to next whole m	new sput volume estimat unber using the following	ion software on site; g rules:
 Any spill volu 	me in less than - I-bbl - is	rounded up to the next 0.	I bbl.		
Examples:		3 bbl Reported vo.			
	Calculated volume = 0	35 bbl Reported vo 31 bbl Reported vo	olume = 0.4 bbl		
and a		·			
wnerever this estimation	i tool is not applicable plea	ise refer to paraeraph 6i	c (Deviations) of th	e 31V procedure to use	announciate stone for

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and ottach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME

	/OFFSHORE (Leak stopped at	source)		
Impacted Area Details		*		400.00
Total Calculated Area of	•			400.00 m²
i Impact within SPDC R.O.I				m² m²
ii Impact outside SPDC R.C	.W			Jm²
Volume of oil recovered before i Estimated Recovered oil (40.00 bbis
				10100,0010
Estimated Recovered of	(Net) V _{recJ}			40.00 bbls
Computation of estimated res	idual volume on site			
a Computation of volume	of free phase oil (on land or confine	d water body)		
i Total area occupied by po	ol of free phase oil			m ²
ii Average depth of pool of f	ree phase oil			m
iii Emulsification factor	(If applicable, else 0%)			<u></u> %
Estimated Volume of po				0.00 m³
Estimated Volume of po	ol of free phase oil, V _{pool}			0.00 bbls
b Computation of estimate	ed volume of infiltrated oil in the soil	(/V)		
Volume of infiltrated oil		1 × 967		
i Total area covered by the				2.00 m ²
•	• •	.dim.a		1.200 m
- ·	n above leaking facility i.e. pipeline/flov	wine		
iii <u>Soil type</u>	iD			Clay
iv P _e (effective porosity of th	5 8OH)			%
v Cause of spill				Third party interference
vi Calculation of days for	rinfiltretion below the leaking point on p	pipeline or flowline]	
Incident Date	JIV Date	Days on Site		
8/21/2014 14:30	8/22/2014 13:24	1		
	rational, use 1 week as worst case there 'davs on site' exceeds 7.	7		
	Infiltration of oil types in various soil t	voes vs time.		٦
Soil type	Approximate time to reach	7.1	nd level	
Oil type	Sand	Loam	Clay	
Bonny Medium	3 weeks	3 years	> 10 years	_
Bonny Light	2 days	2 months	> 10 years	
vii Oil type				Bonny Light
• • • • • • • • • • • • • • • • • • • •	on below leaking facility i.e. pipeline/flow	vline		m
ix Total depth below ground	surface of infiltration of oil			m
Estimated Volume of inf				0.18 m³
Estimated Volume of inf	iltrated oli, V _{irts}			1.21 bbls
2 Volume of infiltrated oil	at second spill point [if applicable] ('V1		
i Total area covered by the		. = anf b f		4.00 m²
•	on above leaking facility i.e. pipeline/flov	wline		1.500 m
iii Soil type	Transfer leaning racing i.e. pipeliterior	THE IS		Clay 🔻
iv P. (effective porosity of th	e soil)			Clay %
10 . B farmana beneatly of the	,			/6
A doub of infiltratio	n halow leaking facility i a nineline/flow	uliaa		

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1235195

Net Total Estimated Spilled Volume, V_{Est}

m.a	WIA. 4 1 41 44			,
Estimated Volume of Inf				0.48 m³
Estimated Volume of Inf	iltrated oil, V heb			3.02 bbis
olume of infiltrated oil	outside immediate spill point(s) reg	ion (Vسم)		
Total Area covered by the		, (- 88 6)		394.00 m ²
Total Area of the pool of free phase oil in touch with soil				m ²
Soil type				Clay
effective porosity of the	e soil)			%
Average depth below grou	and surface of infiltration of oil			m
Estimated Volume of inf	iltrated oil, V _{infe}			0.01 m³
Estimated Volume of inf				0.05 bbla
Estimated Total Volume				0.68 m³
Estimated Total Volume	of infiltrated oil, V _{hr}			4.28 bbls
- •	oil on water based on coloration	Link to Coverage Visual		m²
ipili Factora from USCG FOG	(2000 Edition)	Aid Percentage coverage		1
	Thickness (mm)	(%)	Volume (m3)	
Barely Visible	0.00004		0.0000	
Silvery	0.0008		0.0000	
Slight Color	0.00016		0.0000	
Bright Color	0.0003		0.0000	
Dull	0.001		0.0000	
<u>Dark</u>	0.002		0.0000	
Black oil	0.1		0.0000	
Emulsion (30% Oil)	1		0.0000	
	Percent Total:	0%	0.0000	
stimated Volume of oil	on onen water. V			0.00 m³
atimated Volume of oil				0.00 bbis
lation of evaporated vol	ume			
HUVII VI STADUIAUSU YU				1
	Evaporation Factors (E-Factor) for S	SPDC Crude oil		
	Evaporation Factors (E-Factor) for S of spilled oil (days on site)	Oil ty		
	e of spilled oil (days on site)	Oil ty Bonny Light	Bonny Medium	
	e of spilled oil (days on site)	Oil ty Bonny Light 10%	Bonny Medium 5%	
	of spilled oil (days on site) < 1 day 1-7 days	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	
	e of spilled oil (days on site)	Oil ty Bonny Light 10%	Bonny Medium 5%	
Residence time	c of spilled oil (days on site) < 1 day 1-7 days > 7 days V completion done before JIV date?	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	Yes ▼
Residence time	c of spilled oil (days on site) < 1 day 1-7 days > 7 days V completion done before JIV date?	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	Yes ▼ bbls
Residence time	c of spilled oil (days on site) < 1 day 1-7 days > 7 days V completion done before JIV date?	Oil ty Bonny Light 10% 25%	Bonny Medium 5% 15%	

45.71 bbls

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1235195 JIV report S/N: 00684

23. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

24. REPRESENTATIVES

This report was filled, agreed and signed by the following joint investigation representatives:

- Host Community: ☑
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1235,195 JIV report S/N: 00684

25. Appendix 1: Overview sketch of the site

