

<u>Overview:</u> Part of spill impact on Adibawa Well10S Flowline Right of Way at Edagberi/Betterland. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2015.



<u>Close-up:</u> Tampered nuts on Adibawa Well10S Flowline at Edagberi/Betterland. Picture was taken during Joint Investigation of 10<sup>th</sup> March 2015.