

Overview: Part of spill impact on Agbada 2 Well34S Flowline Right of Way at Omuohia. Picture was taken during Joint Investigation of 3<sup>rd</sup> May 2015.



<u>Close-up:</u> Cut section on Agbada 2 Well34S Flowline at Omuohia. Picture was taken during Joint Investigation of 3<sup>rd</sup> May 2015.

1