

<u>Overview:</u> Part of spill and Fire impact on Mininta Well 003L and Well 003S Communication Box at Elele Alimini. Picture was taken during Joint Investigation of 24th June 2016.



<u>Close-up</u>: Section of cut stainless tube and fire impact on Mininta Well 003L and Well 003S Communication Box at Elele Alimini. Picture was taken during Joint Investigation of 24th June 2016.