

<u>Overview:</u> Part of spill impact on 18" Assa-Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 19<sup>th</sup> August 2016.



<u>Close-up:</u> Tear/inward dent on 18" Assa-Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 19<sup>th</sup> August 2016.