



Overview: Partially removed Oil Boom placed around work area as a precautionary measure during replacement of the failed valve at Nembe creek 2 flow station.



Close-up: Saver-pit source of over flow at Nembe creek 2 flow station in Nembe . Picture was taken during JIV of 28<sup>th</sup> April, 2011



Overview: New valve replacing failed valve at Nembe creek 2 flow station. Picture was taken during JIV of 28<sup>th</sup> April, 2011