



Overview: Hacksaw cuts visible on Well 13L flowline at Akaso. Picture was taken during JIV of 4<sup>th</sup> May, 2011