



Overview: Part of spill impact on 10" Utorogu-UPS right of way at Ughevwighe. Picture taken during Joint Investigation of 28th August, 2011.



Close-up: Spill due to clamp failure on 10" Utorogu-UPS at Ughevwighe. Picture taken during Joint Investigation of 28th August, 2011.