



Overview: Yokri Well 114S flowline at Yokri/Sokebolou being raised for inspection.  
Picture taken during Joint Investigation of 15<sup>th</sup> August, 2011



Close-up: Spill due to corrosion on Yokri Well 114S flowline at Yokri/Sokebolou.  
Picture taken during Joint Investigation of 15<sup>th</sup> August, 2011