



Overview: Part of spill impact on Ekulama1 Well35S flowline right of way at SandSand. Picture was taken during Joint Investigation of 19th December 2011.



Close-up: Outward dent on Ekulama1 Well35S flowline at SandSand. Picture was taken during Joint Investigation of 19th December 2011.