



Overview: Part of spill impact on Nun River Well 15S flowline right of way at Onyoma. Picture was taken during Joint Investigation of 19th January 2012.



Close-up: Spill due to failed damp on Nun River Well 15S flowline at Onyoma. Picture was taken during Joint Investigation of 19th January 2012.