



Overview: Bubbling observed on 20" Buguma-Alakiri pipeline right of way at Bakana. Picture was taken during Joint Investigation of 22<sup>nd</sup> October, 2011.



Close-up: Drilled hole on 20" Buguma-Alakiri pipeline at Bakana. Picture was taken during Joint Investigation of 23<sup>rd</sup> October, 2011.



Close-up: Unsuccessful drill attempts can be seen after plugging the Drilled hole on 20" Buguma-Alakiri pipeline at Bakana.