



Overview: Part of spill impact on 10" Diebu Creek pipeline at Oporoma right of way. Hose used for bunkering can be seen in the photo.



Close-up: One of three illegal fittings on 10" Diebu Creek pipeline at Oporoma. Picture was taken during Joint Investigation of 8th November, 2011.



Close-up: One of three illegal fittings on 10" Diebu Creek pipeline at Oporoma. Picture was taken during Joint Investigation of 9th November, 2011.