



Overview: Part of spill impact on Opukushi Well 34 Flowline at Agbididama & Egbemo_Angalabiri. Picture taken during Joint Investigation of 6th September, 2011



Close-up: Spill due to Internal Corrosion on Opukushi Well 34 Flowline at Agbididama & Egbemo_Angalabiri. Picture taken during Joint Investigation of 6th September, 2011