



Overview: Part of spill impact on Ekulama 2 Well 38L Flowline at Freetown-Kula. Picture was taken during Joint Investigation of 11th Dec. 2012.



Close-up: Failed weld on Ekulama 2 Well 38L Flowline at Freetown-Kula. Picture was taken during Joint Investigation of 11th Dec. 2012.