JOINT INVESTIGATION REPO	PRT FOR INCIDENT NO	0193775841
(Note: As practicable as possible the JIT re	port is to be signed in the f	field by all the participating parties)
A. GENERAL INFORMATION:		
1. Spill incident Number: 77584	2.Type o	f incident* OIL SPILL
3. Name of Location 6" oBIGB	O NORTH -	DGALE PIPELINE
4. Name of nearest communityOGA	LE 5. State: RIV	ERS 6. LGA ELEME
7. Type of Production facility/Installation _	PIPELINE 8. A	sset owner/District NPE PH
B. INCIDENT INFORMATION:		•
9. Details of incident a. Date of incident: 10TH		
b. Date/Period of investigation: 15	TH FEBRUAR	Y, 2012.
c. Description of spill point environm	ent	
Firmed soil	□ Loose soil	Previously excavated area
☐ Under water	□ Swampy	☐ Exposed pipe surface
□ Well Platform (on Water)		□ Rig
d. Description of leak point (tick as a		
	Hack saw cut	☐ Explosive tear,
☐ Complete Rupture	☐ Inward dent,	☐ Well head tampering
☐ Failed Weld-on illegal hot tap v		☐ Missing Pipeline/Flowline)
☐ Crude oil theft (illegal bunkering	-· -	☐ Third party tampering with Clamp
☐ Third party tampering with valv	e setting,	☐ Third party tampering with flange,
☐ External Corrosion	•	□ Internal Corrosion
☐ Saver-pit over flow,	☐ Surge vessel overflow,	□ Outward dent
☐ Flare System/Bund wall Failure	□ Valve Failure	□ com unit failure
□ Cold vent	☐ Relief valve failure	☐ Others (specify)
e. Incident due to:		~ .
Third party interference	□ Operational	Others (enecific

t.	Spill point coordinates	14	1110	0611
	Measuring unit (M)	MINNA	עוועי	13EL 1
	Northing			

Northing: Easting: 521489.61

Page 1 of 9

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0193 775841

C.	RISK ASSESSME	NT			
	10. Type	of environment:			
	Land	□ Swamp	□ Water	□ Seasonal swamp	
	i. Type o	f environment to w	vhich oil has sprea	d:	
	Land	☐ Swamp	□ Water	☐ River (identify)	
	ii. Weathe	er condition			
	Raining 11. Distance from the	□Sunny ne nearest sensitive	e habitat		
	☐ Drinking w.☐ Built up are☐ Farmlands☐ Fish Farm/F	ea Pond cify). NOT A	PPLICABLE	area [,m] [,m] [,m] [,m] [,m] [,m]	•
	□ Booms	□ Trench	□ Dyke		
	Others:	NONE			
	13. Any pictures or	video coverage?		[N] [N]	
	14. Was there any d	isruption to the inv	estigation?	[Y] [N]	
If y	es give brief description	on:	PPI	ICABLE	

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
A	ONE V	VITHIN	A	EA (F IMPACT

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0193 77 5841

16. Crops/Economic Trees

S/N Type of crops	Young	Medium	Matured	Quantity	Comments
NONE	MITHIN	ARI	EA OF	IMPA	ICT.

17. Fish/Nets/Ponds


S/N	Fish/Nets/Por	nds	Description		Quantity/Size	Comments
k 1		١				
H	NF	\/// i	THIN	+RF	A OF	MPACT
		,	1 1 1 1 1	4		

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	ļ	Quantity/Size	Comments
Mr	74.4	Les Times	AREA		10 A 0 T
111		MI II DIII	AKET	1 OF II	MPAC I.

E. GRAPHIC DESCRIPTION OF LEAK POINT (Overview sketch of the site should be added as an appendix 1)

SECTION OF 6" OBIGBO NORTH - DGALE
PIPELINE AT OGALE SHOWING POSITION OF
HACKSAW CUT.



OGALF

KOM KOM
MANIFOLD

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0193 77584

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	MINNA MIZ	BELT
S/N	Northing	Easting
1	91794.25m	521489.63m
2	91775.82M	521489.63m 521489-59m
3	91772 79 m	521468.02 M
4	91797.35 M	521474.23M
		Today (
		16/02/2012

G. INCIDENT INFORMATION:

20	Impacted	Area	Details
ZU.	minacicu	AICA	Details

• 10	otal calculated area of impact	-//	_
• In	npact within SPDC R.O.W		<u> </u>
• In	npact outside R.O.W		_
1. Volume o	f oil recovered before completion of JIV (VrecJ)	;	
	Recovered oil V _{rec} r	NIL	barrels
0. Computat	ion of the residual volume on site		
. Computati	on of volume of pool of free phase oil (on land or co Area (m²) occupied by pool of free phase oil	onfined water body).	_
ii.	Average Depth (m) of pool of free phase oil	0.001	_
iii.	Emulsification factor:	• •	
	iv. Volume of pool of free phase oil. V _{pool} :	0.02	barrels

P. PII Ha

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: b. Computation of volume of infiltrated oil in the soil (V_{inf}) . i. Area (m²) covered by the oil: ii. Area of the pool of free phase oil in touch with soil: iii. Average Depth (m) below ground surface of infiltration of oil: 0.005 iv. Soil type: CLAY $P_{\rm e}$ (effective porosity of the soil). Volume of infiltrated oil. Vinf iv. 1.01 21. Computation of volume of oil on open water based on standard coloration. Total area of oil on open water: ii. Table of average depth of oil on water based on coloration * Thickness Percentage (mm)

Darely Visible	0.00004	<u> </u>				I
Silvery	0.00008					7
Slight Color	0.00015	NO			<u></u>	7
Bright Color	0.0003					7
Dull	0.001	X 20.				7
Dark	0.002	APPL	. [(SAKLE	•	7
Blackoil	0.1					7
Emulsion (30% Oil)	1]
	Percent Total	100	%	Total Volume	NIL	bbl
	iii. Volume of oil	on open water. Vwat	•			barrels

- 22. Calculation of evaporated volume:
 - i. Oil type: BONNY MEDIUM
 - ii. E-Factor: 15%

iii. Volume of evaporated oil. V evan:		barrels
The volume of evaporated on. V evap-	0-18	Carrers

Evapor	ration Factors (E-Fa	actor) for SPDC Crue	de oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25%	15%
	> 7 days	40%	25%

23. Gross Total Estimated Spilled Volume $V_{Est}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{recJ}(bbls) = 0.18 + NIL + 1-01 + 0.02 + NIL = 1.21$

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0193775841

$V_{Est}(bbls)=$	1.2	BARRE	LS		
24. <u>Net</u> V _{pox}	Total Estin	nated Spilled recJ (bbls) =	Volume V Bst (bbls) = 0-18 + NIL	$= V_{evap}(bbls) + 0.6*V_{wat}$ + 1-01+ 0.02+ 1	(bbls) + V _{inf} (bbls) + NIL = 1.21
VEst(bbls)=		BARRE			
VEst(bbls)=	1.2	BARRE	LS	+ 1-01+ 0-02+ 1	SEA COLUMN TO THE SEA COLUMN T

25. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact. After the initial response and therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

26 Signatories

This report was filled and signed on the investigation representatives from

• Host Community
• Department of Petroleum Resources [DPR]:
• National Oil Spill Detection and Response Agency [NOSDRA]:
• Nigeria Police Force [NPF]:
• Nigeria Police Force [NPF]:
• Shell Petroleum Development Company [SPDC]:
• National Retroleum Investment Management Services [NAPiMS]:

Tick as applicable


^{*}Calculation of the respective estimated volume is to be done using the new spill estimation software on site

^{*}Conversion of m3 to barrels is Total volume VT (m3) x 6.29

^{*}Emulsification factor for spill on water to consider is 60% of volume of oil.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: U193 775841

20. Appendix 1: Overview sketch of the site



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 77584193

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
		7
		• /
-		1402/2012
•	1	,



DEPARTMENT OF PETROLEUM RESOURCES

FIELD JOINT INVESTIGATION REPORT

(Note: As practicable as possible the field report is to be signed in the field by all the participating parties)

1. Company SHELL PETROLEUM DEVELOPMENT COMPANY
2.Incident Serial Number 77 5841
3. Name of Location/Facility 6" DBIGBO NORTH - OGALE DELIVERY
4. Type of Incident: (Indicate ✓ where appropriate and X where not applicable)
 Crude Oil Spill Product Spill (Specify) Drilling Mud/Chemicals Spill Fire Others (specify)
5.Details of Incident i. Date of Incident: $ 0 b2 20 2$
ii. Date Reported to the DPR: iii. Date/Period of First Investigation: 15/02/2012
iv. Date/Period of Second/Subsequent Investigation:
v. Cause of Incident (Indicate wwhere appropriate and X where not applicable)
• Corrosion • Equipment Failure • Human Error (Production/Maintenance) • Third Party Interference • Mystery Spill • Others (Specify) Additional description of cause of incident (if any): An approximate I cm hacksand by nak nown person (s) at 110 clock pocition in the delivery line
6.Coordinates of Spill Point/Location(s):
7. Brief Description of Circumstances Around Spill Point(s) (Please indicate containment measures put in place, point of breach along pipeline and any necessary details observed at site. Attach additional sheets if necessary) Before excavation of the Spill point, a gentle obtained of the crude was abserved. On excavation, a cut likely from a hack saw was observed at 110 clock position on the pipeline.
on the hal

8.Delineation of Impacted Area: (Indicate where appropriate to the state of the sta	priate and X where not appli	icable)
a) Within company's facilities/ROW		
b) Outside company's facilities/ROW	L	
9. Description of Environment Around Spill Point/L where not applicable)	ocation(s): (Indicate 🗸 w	here appropriate and X
 Land Seasonal Swamp Swamp Coastland 	Inland watersNear shoreOffshore	
Please provide a graphic sketch of spill site/leak p	o int (Detailed sketches and	mans can he attached whe
fation Billing (" DIL	Hacksawcat	N N
JORTH >- ()	Macsanda	D Olic
Open space including ROW	Impact	
11 11 1/5 11 11	(1 (1 (1	41 17
Table of Key Coordinates of Mapped Area	母母母	1 [
S/N Eastings Northings S.	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S.	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings 521487.63m 91794.25m 521487.63m 91775.82m 521468.81 91772.69m 521468.31 91777.35m	N Eastings	Northings
S/N Eastings Northings S. 521487.63m 91794.25m	N Eastings	Northings
S/N Eastings Northings 521487.63m 91794.25m 521487.63m 91775.82m 521468.81 91772.69m 521468.31 91777.35m	N Eastings	Northings
S/N Eastings Northings 521487.63m 91794.25m 521487.63m 91775.82m 521468.81 91772.69m 521468.31 91777.35m	N Eastings	Northings
S/N Eastings Northings S.	d)	Northings
S/N Eastings Northings S/N 521487.63m 91794.25m 521487.63m 91775.82m 91772.75m 91772.75m 91772.75m 91772.75m 91777.35m 91797.35m 917	d) e)	Northings

make brief comments on quantities unaccounted for. Attach and endorse additional sheets if necessary)

2

13. Quantity Recovered (As at time of the investigation): 14. Any Photograph or Video Recording? (Provide details): Photograph faken but SPDC took video 1 Andres ignation.	
15. Additional Comments/Remarks, if any:	
,	
	•
•	

.

•