THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0206841

(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)

1. Spill incident Number:	A. GENERAL INFORMATION:				
3. Name of Location	^				
4. Name of nearest community	1. Spill incident Number: 8715	2.Type	of incident* UIL SPIEL		
a. Date of incident: b. Start date/time of investigation:	3. Name of Location X ASS	4- Kunuekp	E PIPELINE		
a. Date of incident: b. Start date/time of investigation:	4. Name of nearest community E985	OA 5. State: <u>K</u> 1	VERS 6. LGA EMOHUA		
a. Date of incident: b. Start date/time of investigation:	7. Type of Production facility/Installation	OIL PIPELMES.	Asset owner/ District WG/P/NETP		
a. Date of incident: b. Start date/time of investigation:	B. INCIDENT INFORMATION:				
Firmed soil	9. Details of incident a. Date of incident: / S/W b. Start date/time of investigation: / c. Investigation End date: / 8/W	11/ 2012 8/ JULY 20	512		
Well Plateform (on Water)			Previously excavated area		
e. Description of leak point (tick as applicable); Drilled hole Hack saw cut Spalled Weld-on illegal hot tap valve, Crude oil theft (illegal) bunkering) point, Third party tampering with valve setting, Corrosion Saver-pit over flow, Surge vessel overflow Outward dent Flare System/Bund wall failure Valve Failure Communit failure Relief valve failure Gothers (specify) Incident caused by: Third party interference Gesting: Basting:	Under water	□ _{Swampy}	☐Exposed pipe surface		
Drilled hole			\square_{Rig}		
□ Complete Rupture □ Inward dent, □ Well head tampering □ Failed Weld-on illegal hot tap valve, □ Missing Pipeline/Flowline) □ Crude oil theft (illegal) bunkering) point, □ Third party tampering with Clamp □ Third party tampering with valve setting, □ Third party tampering with flange, □ Corrosion □ Saver-pit over flow, □ Surge vessel overflow □ Outward dent □ Flare System/Bund wall failure □ Cold vent □ Relief valve failure □ Cothers (specify) □ Incident caused by: □ Third party interference □ Operational □ Mystery □ Spill point coordinates □ Measuring unit □ Cold vent □ Co			_		
□ Failed Weld-on illegal hot tap valve, □ Missing Pipeline/Flowline) □ Crude oil theft (illegal) bunkering) point, □ Third party tampering with Clamp □ Third party tampering with valve setting, □ Third party tampering with flange, □ Corrosion □ Saver-pit over flow, □ Surge vessel overflow □ Outward dent □ Flare System/Bund wall failure □ Valve Failure □ com unit failure □ Cold vent □ Relief valve failure □ Others (specify) □ Incident caused by: □ Third party interference □ Operational □ Mystery □ Spill point coordinates □ Measuring unit □ Northing: □ Easting:	☐Drilled hole	Hack saw cut	☐Explosive tear,		
□ Crude oil theft (illegal) bunkering) point, □ Third party tampering with Clamp □ Third party tampering with valve setting, □ Third party tampering with flange, □ Corrosion □ Saver-pit over flow, □ Surge vessel overflow □ Outward dent □ Flare System/Bund wall failure □ Valve Failure □ com unit failure □ Cold vent □ Relief valve failure □ Others (specify) f. Incident caused by: Third party interference □ Operational □ Mystery □ Mystery □ Spill point coordinates □ Measuring unit □ Northing: □ Easting: □ Corrosion □ Third party tampering with Clamp □ Third party tampering with flange, □ Third party tampering with flange, □ Third party tampering with Clamp □ Third party tampering with flange, □ Third party tampering with flange, □ Surge vessel overflow □ Cold vent □ Cold vent □ Mystery □ Mystery □ Third party interference □ Operational □ Mystery □ Third party interference □ Third party tampering with flange, □ Third party tampering with fla	☐Complete Rupture	\square Inward dent,	☐ Well head tampering		
Third party tampering with valve setting, ☐ Third party tampering with flange, ☐ Corrosion ☐ Saver-pit over flow, ☐ Surge vessel overflow ☐ Outward dent ☐ Flare System/Bund wall failure ☐ Cold vent ☐ Relief valve failure ☐ Others (specify) ☐ Incident caused by: ☐ Incident caused by: ☐ Third party interference ☐ Operational ☐ Mystery ☐ Spill point coordinates ☐ Measuring unit ☐ Northing: ☐ Easting:	☐Failed Weld-on illegal hot tap	valve,	☐ Missing Pipeline/Flowline)		
□ Corrosion □ Saver-pit over flow, □ Surge vessel overflow □ Outward dent □ Flare System/Bund wall failure □ Valve Failure □ com unit failure □ Cold vent □ Relief valve failure □ Others (specify) f. Incident caused by: □ Operational □ Mystery g. Spill point coordinates ■ Measuring unit Northing: ■ Easting:	☐Crude oil theft (illegal) bunker	ring) point,	☐ Third party tampering with Clamp		
□ Corrosion □ Saver-pit over flow, □ Surge vessel overflow □ Outward dent □ Flare System/Bund wall failure □ Valve Failure □ com unit failure □ Cold vent □ Relief valve failure □ Others (specify) f. Incident caused by: □ Operational □ Mystery g. Spill point coordinates ■ Measuring unit Northing: ■ Easting:	☐Third party tampering with val	lve setting,	☐ Third party tampering with flange,		
Outward dent	Corresion	☐Saver-pit over flow,			
Valve Failure	Outward dent	☐Flare System/Bund			
f. Incident caused by: Third party interference	<u></u>	_			
g. Spill point coordinates Measuring unit Northing: Easting:	Relief valve failure				
g. Spill point coordinates Measuring unit Northing: Easting:	f. Incident caused by:				
Measuring unit Northing: Easting:	- - /	☐ Operational	Mystery		
		<u> </u>			
139063.1 479298.0	Northing:	"	Easting:		
	139063.1		479298.0		
			·		
ı İ					

Page 1 of 9

^{. *}This can be a) Oil spill b) Drilling fluid/Chemical c) siltation d) construction e) Encroachment f) Fire,

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0206 841174

C.	RISK ASSESSMEN	IT		•
	10. Type o	of environment:		
	Land	□ Swamp	□ Water	☐ Seasonal swamp
	i. Type of	environment to w	hich oil has sprea	d:
	Land	□ Swamp	☐ Water	☐ River (identify)
	ii. Weather	r condition		
	☐ Raining 11. Distance from th	Sunny ac nearest sensitive	e habitat	
	☐ Government ☐ Drinking wa ☐ Built up are: ☐ Farmlands ☐ Fish Farm/P ☐ Fishing net ☐ Others (spec	enter source NC Cond APP cify).	ignated protected :) T LICABLE e;	[NM-,m] [NM-,m]
	□ Booms	Trench	□ Dyke	
	Others:	LATULAL	DEPLESS	urs
	13. Any pictures or	video coverage?		[N]
	14. Was there any d	isruption to the in	vestigation?	[Y] (N)
If	yes give brief descripti	on:		
	MOT	<u> </u>	IICAR	
	1 40 1	+++	ri CW.7	NC .

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

15. Structures / Properties

C.

S/N	Type of Structures	Description	Size	Number	Comments
					ļ
	MARIE	11.77	i ii A	0-1 07	10000
	/ \ \() /\\ C	$\mathcal{M}^{\prime\prime}$	* / // /	KEA UT	MPACI
<u> </u>					
		,			

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 8411719

16. Crops/Economic Trees

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	MAL	WITHM	AOS	A KT	100 00	ा नाई
	110140	MALLO.	, 1/16-6	CV A	111/1/11/11/11/11/11/11/11/11/11/11/11/	\sim 1
			ļ			

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
_	10 -			
$\perp \Delta$	$1/ \setminus 1/ \setminus$	UITHILL AR	th at 1	MONOT
		MICATINA XTKY	IN OF	MITTE

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Qua	intity/Size	Comments	
Δ	MAIL.	1 (1744)	ADATA	NT	IM AACT	
	をしてない	MITHIA	X JOHN	4	Mich VO	
	ı					

E. GRAPHIC DESCRIPTION OF LEAK POINT While detail report of the leak point should be contained in the Leak report, overview sketch of the site should be added as an appendix 1)

SHOWING HACK SAW CUT AT 12 0' Chock POSITION.



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGHT HIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 2411-4

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

19. Impacted area boundary Coordinates (If more than 12 points, Attach as an appendix 2)

	N/G - MID-	-BELT.
S/N	Northing	Easting
WP 252	139 063 · 1	479291.9
WP 253	139066.2	479282.6
WP254	139078:5	479288.8
	139078.5	4792950
WP 256	•	479304.4
	139152.2	479 307.5
WP258	139149.1	479316.7
WP359	139087.7	479304.2
•	·	
-		
I	·	<u> </u>

G. INCIDENT INFÓRMATION:

20.	Impacted	Агеа	Detail	L\$
-----	----------	------	--------	-----

Total calculated area of impact Impact within SPDC R.O.W Impact outside R.O.W	152 0.08891	ha	
21. Volume of oil recovered before comple	tion of JIV (V _{rec.J}):		
Recove	ered oil Viser	NUL	barrels
20. Computation of the residual volume on a. Computation of volume of pool of free pha i. Area (m²) occupied by pool of ii. Average Depth (m) of pool of	se oil (on land or cor f free phase oil	of O-004 m	

THE SHELL PE	TROLEUM D	EVELOPMENT C	OMPAN			
JOINT INVES	STIGATION REF	ORT FOR INCIDE	ENT NO:_	0206	<u>84</u> 1174 -	
iii, Emulsification	factor:	u L				
iv.	Volume of	pool of free phase oil	· V _{pool} :	2.26		barrels
b. Computation of	of volume of infile	trated oil in the soil (V _{inf}).	_		
i		overed by the oil:	80	D M		
ii		ool of free phase oil)m ²	
i	ii Average Dept	th (m) below ground	surface of	infiltration of oi	1: D-002	
i		LAY		<u>سد</u> ـــ		
У	P _e (effective	porosity of the soil).		<u>8% </u>		
ì	v. Volume	of infiltrated oil. V	inf	0.9		barrels
21. Computation	of volume of oil	l on open water bas	sed on sta	ndard coloratio	n.	
-	f oil on open wat	- 411				
ii. Table of ave	rage depth of oil o	on water based on color	ation **			
	Thickness	Percentage	e			
Г	(mm)	coverage		Volume (n3)	
Barely Visible	0.00004	10-	= +			
Silvery Slight Color	0.00008 0.00015	 / /// 				
Bright Color		 				
Dull	0.001	A 0 0				
Dark	0.002	AHY	1 1	A 6 L		
Black oil	0.1					
Emulsion (30% Oil)	1					1
	Percent Total		100%	Total Volume	<u> bbl</u>	.]
ill.		il on open water. V	wat:	NUL	<u></u>	barrels
22. Calculation o						
	ype: BONN					
ii. E-Fa	actor: <u>25</u>	10				
iii.	Volume of e	vaporated oil. V _{emp} :	%	1.05		barrels
		A S COPPO C	.:1			<u> </u>
Oil Type	tion Factors (E-Fac Days on site	ctor) for SPDC Crude Bonny Light	Bonny			
on type	Days on sinc	Doini, Digut	Medium			
Period Since Oil	< 1 day	10%	5%			
Spill		<u> </u>	l			

Evapor	ation Factors (E-Fa	actor) for SPDC Crude	e oil
Oil Type	Days on site	Bonny Light	Bonny Medium
Period Since Oil Spill	< 1 day	10%	5%
	1-7 days	25% 🍑	15%
	> 7 days	40%	25%

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 23. Gross Total Estimated Spilled Volume $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$ VER(bbls)= 1.05+AM+0.9+2.28+AM = 4.21 BARRELS 12 4.2 BARRELS 24. Net Total Estimated Spilled Volume $V_{\text{Est}}(bbls) = V_{\text{evap}}(bbls) + 0.6*V_{\text{wat}}(bbls) + V_{\text{inf}}(bbls) + V_{\text{pool}}(bbls) + V_{\text{recJ}}(bbls)$ VEST(bbls)= 1.05+NU+0-9+2.26+NU-74-21 BARRELSS Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site *Conversion of m3 to barrels is Total volume VT (m3) x 6.29 *Emulsification factor for spill on water to consider is 60% of volume of oil. 25. GENERAL STATUS OF THE SITE A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out B. Investigation of the incident site showed that there is residual impact on site requiring further works 26 REPRESENTATIVES 18/07/20/2 at incident site by joint This report was filled and signed on the investigation representatives from Host Community Department of Petroleum Resources [DPR]: □ National Oil Spill Detection and Response Agency [NOSDRA]: □ State Ministry of Environment [SME]: □ Nigeria Police Force [NPF]: Shell Petroleum Development Company [SPDC]:


 □

Tick as applicable

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 8210674

27. Appendix 1: Overview sketch of the site



THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED JOINT INVESTIGATION REPORT FOR INCIDENT NO: 0206 841174

21. Appendix 2:TABLE SHOWING ADDITIONAL COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

S/N	Northing	Easting
		/-
	/-	
-		
	-	