



Close up: Spill due to corrosion on Obigbo North Well03L flowline at Umuebulu.
Picture was taken during Joint Investigation of 15th June 2012.