



Overview: Part of spill impact on Agbada2 Well69S flowline right of way at Umuokwa. Picture was taken during Joint Investigation of 17th June 2012.



Close up: Illegal fitting on Agbada2 Well69S flowline at Umuokwa. Picture was taken during Joint Investigation of 17th June 2012.