



Overview: Part of spill impact on Imo River Well 64S/L Flowline at Owaza. Picture was taken during Joint Investigation of 22nd Nov. 2012.



Close-up: Hacksaw cut on Imo River Well 64S/L Flowline at Owaza. Picture was taken during Joint Investigation of 23rd Nov. 2012.



Close-up: Missing Flowline on Imo River Well 64S/L Flowline at Owaza. Picture was taken during Joint Investigation of 23rd Nov. 2012.