



Close up: Part of spill impact on Obigbo Well28LS flowline right of way at Umuebulu. Picture was taken during Joint Investigation of 15th November 2012.



Close up: Cut sections on Obigbo Well28LS flowline at Umuebulu. Picture was taken during Joint Investigation of 15th November 2012.