




Overview: Part of spill impact on Imo River Well 33L Flowline at Owaza. Picture was taken during Joint Investigation of 14th Sept. 2012.



Close-up: Illegal fitting on Imo River Well 33L Flowline at Owaza. Picture was taken during Joint Investigation of 14th Sept. 2012.