



Close up: Spill due to corrosion on Bonny Well2S flowline at Oloma. Picture was taken during Joint Investigation of 15<sup>th</sup> September 2013.