



Close up: Hacksaw cut on 4" Adibawa Well8S flowline at Edagberi. Picture was taken during Joint Investigation of 12th April 2013.



Close up: Location of missing bolt and nut on 4" Adibawa Well8S flowline at Edagberi. Picture was taken during Joint Investigation of 12th April 2013.