



Close up: Hacksaw cut on 4" Adibawa Well10S flowline at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.



Closeup: Hacksaw cut on 4" Adibawa Well10S flowline at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.



Close up: Hacksaw cut on 4" Adibawa Well10S flowline at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.



Close up: Hacksaw cut on 4" Adibawa Well10S flowline at Edagberi. Picture was taken during Joint Investigation of 10th April 2013.