



Overview: Part of spill impact on Adibawa Well2S flowline right of way at Edagberi. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2013.



Close up: Drilled hole on Adibawa Well2S flowline at Edagberi. Picture was taken during Joint Investigation of 30<sup>th</sup> April 2013.