



Overview: Part of spill impact on 4in Adibawa North East flowline right of way at Biseni. Picture was taken during Joint Investigation of 28th August 2013.



Close up: Tampered clamp on 4in Adibawa North East flowline at Biseni. Picture was taken during Joint Investigation of 29th August 2013.