



Overview: Part of spill impact on 8" Isimiri-Imo River pipeline right of way at Obiakpu. Picture was taken during Joint Investigation of 9<sup>th</sup> August 2013.



Close up: Illegal fitting on 8" Isimiri-Imo River pipeline at Obiakpu. Picture was taken during Joint Investigation of 9<sup>th</sup> August 2013.