




Overview: Part of spill impact on 4" Well69S Flowline right of way at Umuokwa. Picture was taken during Joint Investigation of 3rd January 2014.



Close-up: Failed clamp on 4" Well69S Flowline at Umuokwa. Picture was taken during Joint Investigation of 3rd January 2014.