



Overview: Part of spill impact on 20" Otumara – Escravos Pipeline right of way at Adjudaibo. Picture was taken during Joint Investigation of 17<sup>th</sup> December 2013.



Close-up: Illegal fitting on 20" Otumara – Escravos Pipeline at Adjudaibo. Picture was taken during Joint Investigation of 17<sup>th</sup> December 2013.