



Overview: Part of spill impact on 6" Obigbo North – Ebubu Pipeline right of way at Obolo. Picture was taken during Joint Investigation of 6<sup>th</sup> December 2013.



Close-up: Spill due to corrosion on 6" Obigbo North – Ebubu Pipeline at Obolo. Picture was taken during Joint Investigation of 6<sup>th</sup> December 2013.