



Overview: Part of spill impact on Obigbo Well 9L flowline right of way at Umuebulu. Picture was taken during Joint Investigation of 15th February 2013.



Close up: Hacksaw cut on Obigbo Well 9L flowline at Umuebulu. Picture was taken during Joint Investigation of 15th February 2013.