



Overview: Part of spill impact on Imo River Well22S flowline right of way at Igirukwu. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2013.



Close up: Cut section on Imo River Well22S flowline at Igirukwu. Picture was taken during Joint Investigation of 3<sup>rd</sup> July 2013.