



Overview: Part of spill impact on 3" Imo River Well5L flowline right of way at Igiriukwu. Picture was taken during Joint Investigation of 1<sup>st</sup> August 2013.



Close up: Cut section on 3" Imo River Well5L flowline at Igiriukwu. Picture was taken during Joint Investigation of 1<sup>st</sup> August 2013.