




Overview: Part of spill impact on 36" Nkpoku-Bomu pipeline right of way at Akpajo. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Akpajo. Picture was taken during Joint Investigation of 14<sup>th</sup> May 2013.



Close up: Illegal fittings on 36" Nkpoku-Bomu pipeline at Akpajo. Picture was taken during Joint Investigation of 15<sup>th</sup> May 2013.