



Close-up: Spill due to corrosion on 6" Obigbo-North - Ebubu Pipeline at Obolo. Picture was taken during Joint Investigation of 21st October 2013.