



Overview: Part of spill impact on 4" Imo River Well 53L/56L Flowline at Etitioha-lpu  
Picture was taken during Joint Investigation of 9<sup>th</sup> October 2013.



Close up: Missing flowline on 4" Imo River Well 53L/56L Flowline at Etitioha-lpu .  
Picture was taken during Joint Investigation of 9<sup>th</sup> October 2013.