



Overview: Part of spill impact on 20" Otumara-Escravos trunkline right of way at Adjudaibo. Picture was taken during Joint Investigation of 12th September 2013.



Close up: Illegal fitting on 20" Otumara-Escravos trunkline at Adjudaibo. Picture was taken during Joint Investigation of 12th September 2013.



Close up: Illegal fitting on 20" Otumara-Escravos trunkline at Adjudaibo. Picture was taken during Joint Investigation of 12th September 2013.