



Overview: Part of spill impact on 4" Adibawa Well10S Flowline right of way at Adibawa. Picture was taken during Joint Investigation of 10th April 2014.



Close-up: Hacksaw cut on 4" Adibawa Well10S Flowline at Adibawa. Picture was taken during Joint Investigation of 10th April 2014.