



Overview: Bubbling and oil sheen observed on Otumara Well41S Flowline right of way at Ugboegungun. Picture was taken during Joint Investigation of 17th April 2014.



Close-up: Tear on Otumara Well41S Flowline at Ugboegungun. Picture was taken during Joint Investigation of 17th April 2014.