



Overview: Part of spill impact on Otumara Well34L/S Flowline right of way at Ugboegungun. Picture was taken during Joint Investigation of 22nd January 2014.



Close-up: Illegal fittings on Otumara Well34L/S Flowline at Ugboegungun. Picture was taken during Joint Investigation of 22nd January 2014.