


Overview: Part of spill impact on Imo River Well1T Flowline Right of Way at Igiriukwu (Owaza). Picture was taken during Joint Investigation of 17th June 2014.



Close-up: Drilled hole on Imo River Well1T Flowline at Igiriukwu (Owaza). Picture was taken during Joint Investigation of 17th June 2014.