



Overview: Part of spill impact on Nembe 1 Well 23T Flowline at Nembe Creek. Picture was taken during Joint Investigation of 25<sup>th</sup> July 2014.



Close-up: Spill due to corrosion on Nembe 1 Well 23T Flowline at Nembe Creek . Picture was taken during Joint Investigation of 26<sup>th</sup> July 2014.