



Overview: Part of spill impact on Opukushi Well24T Flowline at Egbemo-Angalabiri. Picture was taken during Joint Investigation of 20<sup>th</sup> March 2014.



Close-up: Spill due to corrosion on Opukushi Well24T Flowline at Egbemo-Angalabiri. Picture was taken during Joint Investigation of 20<sup>th</sup> March 2014.