,0	INT INVESTIGATION REPORT FOR I	•	•	
	(Note: As practicable as possible the JII	report is to be signed in the	field by all the participating parties)	
	A. GENERAL INFORMATION:	·		
	1. Spill incident Number: 1140	4 15 2.Type	of incident* OIL SPILL	
	3. Name of Location 24" BON			
	4. Name of nearest community FREE	TOWN 5. State: Ru	VERY 6. LGA ANDOMI	
	7. Type of Production facility/Installatio	n OIL PIPKINE 8.	Asset owner/District PIPELINE	
	B. INCIDENT INFORMATION:			
	9. Details of incident a. Date of incident: 15 m b. Start date/time of investigation:		14 1 151420m.	
			estigation duration, days: ONE(1) 1AY	
	d. Description of spill point enviro	onment		
		_	П	
	☐Firmed soil ☐Under water ☐Well Platform (on Water)	□Loose soil ☑Swampy	☐ Recently excavated area ☐ Exposed pipe surface ☐ Drill Rig	
	Under water	⊠ Swampy •	Exposed pipe surface	
	☐Under water ☐Well Platform (on Water)	Swampy . spill point:	Exposed pipe surface	
	Under water Well Platform (on Water) Additional observations around the	spill point: BLE as applicable);	Exposed pipe surface	
	Under water Well Platform (on Water) Additional observations around the state of the platform (on Water) Additional observations around the state of the platform (on Water) Additional observations around the state of the platform (on Water) Additional observations around the state of the platform (on Water) Additional observations around the state of the platform (on Water) Additional observations around the state of the platform (on Water)	Swampy spill point: BLE	Exposed pipe surface Drill Rig Tear (
	Description of leak point (tick a	spill point: BLE as applicable); Hack saw cut Inward dent,	□ Tear (
	Description of leak point (tick a Complete Rupture Complete Rupture	spill point: BLE as applicable); Hack saw cut Inward dent, valve, □Failed Clamp	□ Exposed pipe surface □ Drill Rig □ Tear (_
	Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap was a complete Rupture Crude oil theft (illegal bunks)	spill point: BLE as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point,	☐ Exposed pipe surface ☐ Drill Rig ☐ Tear (
	Description of leak point (tick a Drilled hote Complete Rupture Failed Weld-on illegal hot tap was a Crude oil theft (illegal bunkt Third party tampering with the Complete Rupture Ru	spill point: BLC as applicable); Hack saw cut Inward dent, valve, I Failed Clamp ering) point, valve setting,	Exposed pipe surface Drill Rig Tear (
	Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap value oil theft (illegal bunke with a party tampering with value)	spill point: BLE as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow,	□ Exposed pipe surface □ Drill Rig □ Tear (
	Description of leak point (tick a Drilled hote Complete Rupture Failed Weld-on illegal hot tap value oil theft (illegal bunkt Third party tampering with value) Bulging Outward	spill point: BLC as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund v	□ Exposed pipe surface □ Drill Rig □ Tear (
	Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap value oil theft (illegal bunks Third party tampering with value) Bulging Outward impact Valve Fail	spill point: BLE as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund value	□ Exposed pipe surface □ Drill Rig □ Tear (
	Description of leak point (tick a Drilled hote Complete Rupture Failed Weld-on illegal hot tap value oil theft (illegal bunkt Third party tampering with value) Bulging Outward	spill point: BLC as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund v	□ Exposed pipe surface □ Drill Rig □ Tear (
	Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap version of Drilled hole Crude oil theft (illegal bunks of Third party tampering with version Drilled hole Corrosión Bulging Outward impact Valve Failed Relief valve failure	spill point: BLE as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund value Others (specify)	□ Tear (
	Description of leak point (tick a Drilled hole Complete Rupture Failed Weld-on illegal hot tap value oil theft (illegal bunks Third party tampering with value of the Corrosión Bulging Outward impact Valve Failed Relief valve failure f. Incident caused by: Third party interference (Sabota	spill point: BLE as applicable); Hack saw cut Inward dent, valve, Failed Clamp ering) point, valve setting, Saver-pit over flow, Flare System/Bund value Others (specify)	□ Exposed pipe surface □ Drill Rig □ Tear (

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

g. Spill point coo	rdinates			ın	IA /AIA	Min-	RELT
Northing:				Easting:	<u> </u>	771112	
	57 456	97		5	304	+34	·3 <i>5</i>
C. RISK ASSESSMI	ENT						
10. Typ	e of environment:						
□Land	Swamp	□Water	□Sea	sonal swamp	□Shoreli	ne/Waterfro	ont
і. Туре	of environment to	which oil has spi	read:				
□Land	⊠ Swamp	□Water	□Riv	er (identify)_			
ii. Weat	her condition						
□Rain 11. Distance from	Sunny the nearest sensiti	-	□Wet	□Windy		Hot [Cool
DrinkingBuilt up a	area NON is n/Pond WIT et	e Ste	시	1, , , , , , , , , , , , , , , , , , ,	n] n]		
12. Containment	measures put in pla	ace;					
□Booms □Others:_	Trench	Dyke	□Na	tural depressi	on 🏻	Pit	None
	or video coverage?	?			N]		
13. Any pictures		d as at the time o	f JIV?	W [N]		
	onse/repair initiate					.2. 1 1	rΩn ι.
14. Further response	ef description;		ENT	0F 71	te S	<u>, የ፤ ኒኒ</u>	<u>- </u>
If yes to item 14, give bri	ef description;	SSESSIM S REON		OF IV	te S	YILL	<u>- 701A</u>
14. Further respondent of the CARRICA OUT OUT	ef description;	SSESSIM S REON			HE S	714	<u>- /\u014</u>

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1140415 JIV report S/N: 0494

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N	Type of	Structures	Description	Size	Number	Comments
M	ONE	Jalijn	1N "	AREA	OF	IMPAET
1	7. Crops/I	Economic Trees		<u> </u>		

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	ONE	i Hin	ADR	A OF	Treson	P /
/ 4	- /	MITHIA	<i>///</i> /		24"	

18. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/		
Ą	ONE	Willin	AXCA	OF IMPHE	ī —

19. Others (Specify) i.c. Animal Traps

S/N	Others	Description		Quantity/Size	Comments
M	one	WHIM	AREA	OF I	MAPACT
L					

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the

HOWING POSITION OF CORROSION AT 5 O'CLOCK POSITION.



JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1/40415 JIV report S/N: 0494

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION 20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

	MINNA MID-BELT
Northing (M)	Easting (m)
57 470.76	53 04 28.92
57 476. 13	53 04 41 . 44
57 476.13	5304 50.83
57 492.63	53 04 64.24
57 487 75	530466 . 47
57 472.55	53 0453 51
57 471.66	53 04 53 · 06
57 467.19	53 04 52 . 17
57 458.24	53 04 45. 46
57 450.20	530435.18
57460.07	530418.94
. /	
/.	·
. /	
	57 476. 13 57 476. 13 57 492. 67 57 487. 75 57 472. 55 57 471. 66 57 467. 19 57 458. 24 57 450. 20

OINT INVESTIGATION REPORT FOR INCIDENT NO: 1140415 JIV report S/N:	0494
G. INCIDENT INFORMATION:	
20. Impacted Area Details	
Total calculated area of impact O-06 Hq	_
Impact within SPDC R.O.W	
Impact outside SPDC R.O.W YES	
21. Volume of oil recovered before completion of JIV (V _{rec}):	
Recovered oil V _{recl} : MIL	Barrels
Controlled recovery/evacuation from source with no impact to environment:	
MOT APPLICABLE Barrels	
14 - 1 / 1/1 L. C/17/2 C	
22. Net Estimated Spilled Volume V _{Est} (bbls)* =	
22. Net Estimated Spined Volume V _{Est} pois).	
1.91 BARRELS	
Estimated Reported Volume** V _{rep} (bbls)= 2 BARRELS	
L Driving US	
*Notes: • Volume estimation was done using an excel based tool.(see attached for details on the calculation) • Reported spilled volume is an estimate	
Write other relevant notes taken into consideration for estimating the spilled in the box below:	
SEE AITACHED.	
·	
Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estim Conversion of m' to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the follows:	
 Any spill volume in excess of -1 bbl - is rounded up to the next whole number. 	
 Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl. 	
Examples: Calculated volume = 15.3 bbl Reported volume = 16 bbl	
Calculated volume = 0.35 bbl Reported volume = 0.4 bbl Calculated volume = 0.01 bbl Reported volume = 0.1 bbl.	
Сансинае соните — 0.01 ил Reported Volume — 0.1 ил.	

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME

v Average depth of infiltration below leaking facility i.e. pipeline/flowline

29 1141 311 911 91	THE POLUME			
OIL SPILLED ONSHORE	E/OFFSHORE (Leak stopped at	source)		
Impacted Area Details		-		
Total Calculated Area o	f Impact			600.00 m²
i Impact within SPDC R.O.	w			m²
ii Impact outside SPDC R.0				m²
•				
Volume of all recovered beto	re completion of JiV (V)			
i Estimated Recovered oil	(Net)			0.00 bbls
Entire and Branch of	U AL-A V			***
Estimated Recovered o	II (Mar) A ^(Mo)			0.00 fible
Computation of estimated re	sidual volume on site			
	of free phase oil (on land or confine	d water body)		
i Total area occupied by po				15,00 m²
# Average depth of pool of	•			0.001 m
iii Emulsification factor	(If applicable, else 0%)			%
	ool of free phase oil, V _{pool}			0.02 m³
Estimated Volume of po	ool of tree phase oil, V _{sool}			0.09 bbis
h Committee of estimat	والمراجعة المراجعة ا	100 Y		
	ed volume of infiltrated oil in the soil	(V int)		
Volume of infiltrated oil Total area servered by the	* * * ****			2.00 m²
i Total area covered by the	r on (minutation) on above leaking facility i.e. pipeline/flor	udina		1.000 m
iii <u>Soil type</u>	on above leaking racility i.e. pipelinerito	WIN RC		Clay
iv P. (effective porosity of the	ne soll)			2 1 %
	•			×:
v Cause of spill				Third party interference
			7	
	r inflitration below the leaking point on p		4	
Incident Date	JIV Date	Days on Site	4	
15/03/2014 15:30	21/03/2014 13:46	6	4	
	vational, use 1 week as worst case where days on site exceeds 7.	7		
			-	_
	Inflitration of oil types in various soil I			
Soll type	Approximate time to reach		 	4
Oil type	Sand	Loem	Cley	-
Bonny Medium	3 weeks	3 years	> 10 years	┥
Bonny Light	2 days	2 months	> 10 years	
vii Oil type				Bonity Light
	on below leaking facility i.e. pipeline/flor	Mine		m
TIII 7 TO 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	on room points to the population	*****		
ix Total depth below ground	surface of infiltration of oil			m
				· .
Estimated Volume of In	filtrated oil. V			0.16 m ³
Estimated Volume of in				1.01 bbis
	<u> </u>			
2 Volume of infiltrated oil	at second spili point [if applicable] ((V _{MCb})		
i Total area covered by the	oli (infiltration)			m²
-	on above leaking facility i.e. pipeline/flo	wiine		<u> </u>
III <u>Soil type</u>				- Select - ▼
iv P. (effective porosity of the	ne son)			%

etimated Volume of I-S	Hermon att 14			2 - 2 - 3
estimated Volume of Infl Estimated Volume of Infl			.	0.00 m³
- CHINDLINE TUNNED THE	INGRAM ONE A PAP	<u>.</u>		0.00 bbls
olume of infiltrated oil o	outside immediate spill point(s) reg	ion (V _{info})		
otal Area covered by the				400.00 m²
otal Area of the pool of fro	ee phase oil in touch with soil			m²
oil type				Clay
(effective porosity of the	soil)			*************************************
verage depth below groud	nd surface of infiltration of oil			THE LEASE TO THE M
stimated Volume of Infli	Krated oll, V _{info}			0.05 m³
stimated Volume of infl	ttrated oil, V _{io(s}	•		0.33 bbls
ationated Tatal Malessa	of lathers at all 10			
stimated Total Volume (stimated Total Volume)	of infiltrated oil V			0.21 m³
				1,34 bbls
amandellan of values a		dand anlamaine		
otal area of oil on open w	of oil on open water based on stand ofer			m²
•	ater oil on water based on coloration			""
and or aterage achit (it i	OF OU WATER DAISON OF COUNTRION	Link to Coverage Visual	_	
pill Factors from USCG FOG (2000 Edition)	Ald		,
	Thickness (mm)	Percentage coverage (%)	Volume (m3)	
Barety Visible	0.00004		0.0000	
Silvery	0.0000.0		0.0000	1
Slight Color	0.00015		0.0000	1
Bright Color	0.0003		0.0000	1
Duit	0.001		0.0000	
Dark	0.002		0.0000	
Black oil	0.1		0.0000	
Emulsion (30% Oil)	1		0.0000	
	Percent Total:	0%	0.0000	
				•
	on open water, V			0,00 m³
stimated Volume of oil				0.00 bbis
stimated Volume of oil	on open water, V _{wet}			_
stimated Volume of oil	on open water, V _{wet}			_
stimated Volume of oil of ation of evaporated volume	on open water, V _{wet}]
stimated Volume of oil of ation of evaporated volume	on open water, V _{ent} une Evaporation Factors (E-Factor) for S	Oil to	уре	_
stimated Volume of oil of ation of evaporated volume	on open water, V _{ent} une Evaporation Factors (E-Factor) for S	Oil to	/pe Bonny Medium	
stimated Volume of oil of ation of evaporated volume	on open water, V _{ent} une Evaporation Factors (E-Factor) for S	Oil ty Bonny Light 10%	Bonny Medium 5%	
stimated Volume of oil of ation of evaporated volume	ime Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	
stimated Volume of oil of ation of evaporated volume	ime Evaporation Factors (E-Factor) for S of spilled oil (days on site)	Oil ty Bonny Light 10%	Bonny Medium 5% 15%	
ation of evaporated volume Residence time	on open water, V _{mil} Ima Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days >7 days	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	
ation of evaporated volu	on open water, V _{wel} Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days >7 days / completion done before JIV date?	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	No Ψ
ation of evaporated volume Residence time	on open water, V _{wel} Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days >7 days / completion done before JIV date?	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	No ▼
ation of evaporated volu- ation of evaporated volu- E Residence time /as oil recovery before JiN stimated volume available	on open water, V _{wel} Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days >7 days / completion done before JIV date?	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	bbls
ation of evaporated volu	on open water, V _{wel} Evaporation Factors (E-Factor) for S of spilled oil (days on site) <1 day 1-7 days >7 days / completion done before JIV date?	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	
ation of evaporated volu- ation of evaporated volu- E Residence time /as oil recovery before JiN stimated volume available	on open water, V _{min} Evaporation Factors (E-Factor) for S of spilled oil (days on site) < 1 day, 1-7 days > 7 days / completion done before JIV date? of for evaporation	Oil to Bonny Light 10% 25%	Bonny Medium 5% 15%	bbls

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1140415 JIV report S/N: 0494
--

23. GENERAL STATUS OF THE SITE

A.	Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

24. REPRESENTATIVES

This report was filled, agreed and signed by the following joint investigation representatives:

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- Nigeria Police Force [NPF]: 2
- Sheli Petroleum Development Company [SPDC]:
- Separate DPR form has been filled out with same findings

 ☐

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 11404 15 JIV report S/N:

0494

25. Appendix 1: Overview sketch of the site

