JOINT INVESTIGATION REPORT FOR IN	ICIDENT NO: 118E) 0 02 JIV report S/N:	0522
(Note: As practicable as possible the JIT	report is to be signed in th	he field by all the participating	g parties)
A. GENERAL INFORMATION:			
1. Spill incident Number: 186	002 2.Tyr	oe of incident* OIL	SPILL
3. Name of Location DIEB	4 CREEK	FLOW ST	ATION
4. Name of nearest community ERE	MABIRI_5. State:B	AYELSA6. LGA <u>So</u> i	ATHERN LJAV
7. Type of Production facility/Installation	FLOW STATION	. Asset owner/District	ND 2
B. INCIDENT INFORMATION:			
9. Details of incident a. Date of incident:	H_MAY, 2	lo14	1
b. Start date/time of investigation:	20TH	MAY, 2014	/13: 16 Hours
c. Investigation End date: 201	H MAY Actual in	vestigation duration, days:	NE (1) DAY
d. Description of spilt point enviro	2014	_	, , , , , ,
Firmed soil	Loose soil	Recently excavated a	геа
Under water	☐Swampy	Exposed pipe surface	
Well Platform (on Water)	•	□Dril! Rig	
Additional observations around the s THE POSITION OF POINT) AT THE FL ON WATER). THERE OF THE SAVER PIT, BE	pill point: A BO THE SAV OW STATION WERE CRUDE FING THE IMPA	OM WAS OBS ER PIT (BEING (BEING A GRA OIL STAINS O CT OF THE CRUD	SERVED AT THE SPILL TING PLATFORM N ONE SIDE E OIL SPLASH.
e. Description of leak point (tick a	· · · · · · · · · · · · · · · · · · ·	_	
□ Drilled hole	☐ Hack saw cut	☐ Tear (),
Complete Rupture	□lnward dent,	□Well head tampering	•
Failed Weld-on illegal hot tap v		☐Missing Pipeline/Flo	
Crude oil theft (illegal bunke		☐Third party tampering	
☐Third party tampering with v☐Corrosión	Saver-pit over flow	☐Third party tampering v, ☐Surge vessel overflow	
Bulging Outward	•	wall failure Accidental	
impact	•		d vent
Relief valve failure			
f. Incident caused by:	S!	ZAS BUBBLI NG PLASH FROM S	AVER PIT
Third party interference (Sabota			
	gent, crude metter, Ettle s (including Mystery spills		umagota j
	,	·	

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

INT INVESTI	IGATION F	REPORT FOR IN	CIDENT NO:	1180) 	ort S/N:	0522
g. Sp	ill point coo	ng unit M		M inni	A (M10-	किट्यां)	
	Northing:				Easting:		
		720	73.60		40.	5961.	68
					•		
			\	+	<u>.</u>	$\overline{}$	
					<u></u>		`
C. RISK A	ASSESSMI Tvn	E N I e of environment:					
	JLand	Swamp	Water	Пе	easonal swamp	iboreline/Wa	terfront
_		•	•		sasonar swamp 🗀 s	morenne wa	ternont
_	• •	of environment to	,	_			
	Land	□Swamp	Water	□R	iver (identify)		
	ii. Weat	her condition					
	Rain	Sunny the nearest sensit	Dry tive habitat	□wet	□Windy	□Hot	□cool
C C C	Drinking Built up a Farmland Fish Farm Fishing n	s 1/Pond			[,m] ,m] ,m] [,m] [,m] 30 m		
12. Co	ontainm ent 1	measures put in pl	lace;				
· -	Booms Others:_	Trench	□Dyke	□N	atural depression	□Pit :	□None
13. A	ny pictures o	or video coverage	?		[X] [N]		
14. F	urther respo	onse/repair initiate	ed as at the time	e of JIV?	[Y] [NJ	/	
	•	ef description:		:	•		
	N		100	100	() + 1.	· · · · · · · · · · · · · · · · · · ·	
	140		APPL	$\mathcal{A} \cup \mathcal{F}$	IBLE		
15. W	as there any	disruption to the	investigation?		[Y] [N]		
If yes to ite	em 15 give b	orief description:					
	1	NAT	$-\Lambda$	ĎDI 1	1 ARI	F	
			<i>[</i> 71]	1 T I 1	しょけしし	. L'a	

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1180002 JIV report S/N: 0522

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

16. Structures / Properties

S/N Type of Struct	ures Desc	cription Siz	е Миг	mber		Comments	
NONE	W	THIN	ARE	A O	F	MPAC	T
17. Crops/Econom	Young	Me	dium Ma	tured	Quantity	у Сотт	ents
NONE	WAT	HIN	ARE	A 0	F	MPA CT	-

18. Fish/Nets/Ponds

S/N	Fish/Nets/Ponds	Description		Quantity/Size	Comme	nts
1	ONE	WITHIN	AR	EA ()F	IMPACT

19. Others (Specify) i.e. Animal Traps

S/N	Others		Description	on		Quantity/S	Size	Comm	ents	-
			i							
Δ	ALL.		IJ .	}	Λ.	T. A		-	140	107
\perp		$\Lambda \Lambda$	$H \cap H$		AK	FA			TIVI Y	A ('
" 1	,0,1	4	F. 1. 1. 1	111	11	, , ,		•		

tketch of the site should be added as an appendix 1) FLOW STATION (SCHEMATIC DIAGRAM) GAS . EAK POINT) IN SCRUBBER LQUID (NEAR LEVEL SAVER PIT (IDENTIFIED LIQUID (WATER) POINT OF LEAK) WHERE OIL CORK VALVE Subbling COMPARTMEN NDUCED Page 3 of 8 SEPARATO

LINE

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 180002 JIV report S/N: 0522

F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

20. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

co:	33 07	141 4 4 4 1 1	CHILD SCELLY
S/N	Northing	Meters	Easting NETERS
		73071.75	405958.77
		73074.83	405 % 84
		73072-88	405963.87
		73071.75 73074.83 73072.88 73068.89	405958·77 405961·84 405963·87 405959·74
r ·-	<u> </u>		
ı			
]			
		<u> </u>	
1			
,		/	
-			
	//		
/	/		
	1	·	
<u> </u>			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 180002 JIV report S/N:	0522
G. INCIDENT INFORMATION:	
20. Impacted Area Details	

•	Total calcu	lated area of impact	0)·0014ftq	
•	Impact wit	hin SPDC R.O.W	•	(ēs	
•	Impact out	side SPDC R.Q.W		No	
21. Volume	of oil recov	ered before completion	on of JIV (V	V _{recJ}):	
		Recov	ered oil V _{rec}	i NIL	Barrels
Controlled	recovery/e	vacuation from source	e with no in	npact to environment:	
		NIL	Barrels]	

22. Net Estimated Spilled Volume V _{Est} (bb)	ls)* = 0.23	
Estimated Reported Volume** V _{rep} (bbls)=	D.3 BARREL	

*Notes:

Volume estimation was done using an excel based tool (see attached for details on the calculation)

Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

BASED ON THE OBSERVATION ON SITE THAT THE EXTENT OF IMPACTED AREA WAS WITHIN THE DEPLOYED BOOM, ESTIMATION OF SPILL WAS TREATED AS WITHIN A CONFINED WATER BODY.

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m^3 to barrels is Volume (m3) x 6.29: **Round up estimated volume to next whole number using the following rules:

Any spill volume in excess of 1 bbl is rounded up to the next whole number.

Any spill volume in less than - I bbl - is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl Calculated volume = 0.35 bbl ------ Reported volume = 0.4 bbl Calculated volume = 0.01 bbl ------ Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME OIL SPILLED ONSHORE/OFFSHORE (Leak stopped at source) Impacted Area Details Total Calculated Area of Impact 14.00 m² i Impact within SPDC R.O.W 14.00 ii Impact outside SPDC R.O.W 0.00 1 Volume of oil recovered before completion of JiV (V_{mol}) i Estimated Recovered oil (Net) 0.00 bbls Estimated Recovered oil (Net) V_{rec.} 0.00 bbls 2 Computation of estimated residual volume on site Computation of volume of free phase oil (on land or confined water body) i Total area occupied by pool of free phase oil 14.00 m² ii Average depth of pool of free phase oil 0.002 m iii Emulsification factor (If applicable, else 0%) 0.000 % Estimated Volume of pool of free phase oil, V_{po} 0.03 m³ Estimated Volume of pool of free phase oil, Vp 0.18 bbfs Computation of estimated volume of infiltrated oil in the soil (V int) 1 Volume of infiltrated oil at spill point (V_{int a}) i Total area covered by the oil (inflitration) ii Average depth of infiltration above leaking facility i.e. pipeline/flowline iii Soil type iv Pa (effective porosity of the soil) v Cause of spill Operational Calculation of days for infiltration below the leaking point on pipeline or flowline **incident Date** JIV Date Days on Site 5/18/2014 13:25 5/20/2014 13:20 If 'cause of spill' is operational, use 1 week as worst case scenario except where 'days on site' exceeds 7. Infiltration of oil types in various soil types vs time. Soil type Approximate time to reach 1m depth below ground level Clay Oil type Sand Loam Bonny Medium 3 years > 10 years Bonny Light 2 days 2 months > 10 years

· · · · · · · · · · · · · · · · · · ·	
ii Oil type	Bonny Light ▼
ii Average depth of infitration below teaking facility i.e. pipeline/itowtine	m
x Total depth below ground surface of infiltration of oil	m
Estimated Volume of Infiltrated oil, V infa	0.00 m ³
Estimated Volume of Inflitrated oil, V inf a	0.00 bbls
• Volume of infiltrated oil at second spill point [if applicable] (V _{inth.})	
Total area covered by the oil (infiltration)	m²
Average depth of infiltration above leaking facility i.e. pipeline/flowline	m
Soil type	- Select -
P _e (effective porosity of the soil)	%
Average depth of infiltration below teaking facility i.e. pipetine/flowline	m
i Total depth below ground surface of infiltration of oil	, m
Estimated Volume of inflitrated olf, V inf b	0.00 m³
Estimated Volume of inflitrated oil, V by b	0.00 bbls

3 Volume of infiltrated oil outside immediate split point(s) region (V_{info})

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 180002

¡ Was oil recovery before JIV completion done before JIV date?

il Estimated volume available for evaporation

Estimated Volume of evaporated oil, Veve

Net Total Estimated Spilled Volume, V_{Est}

iii *E-fact*or

n touch with soil Infiltration of oil Infiltration of oil Info			
infiltration of oil			- Select - ₩ % m
de de			% m 0.00 m³
de de			0.00 m³
de de			0.00 m³
od, V _{int}			
od, V _{int}		_	
oil, V _{inf} oil, V _{inf}			
oli, V _{inf}			1
ois, V _{inf}			0.00 m ³
			0.00 bbls
	Link to Coverage Visual.		m²
	Percentage coverage		
išckness (mm)	(%)	Volume (m3)	
0.00004		0.0000	
80000.0		0.0000	
0.00015	<u> </u>	0.0000	
0.0003		0.0000	
0.001	_	0.0000	
0.1			
Demant Totals			
— Percent Ioui:	0%	0.0000	
r, V _{wat}			0.00 m ³
			8ldd 00.0
	0.00008 0.00015 0.0003	Link to Coverage Visual Aid	Link to Goverage Visual Aid Percentage coverage (%) Volume (m3) 0.00004 0.00000 0.00005 0.00000 0.0001 0.00000 0.001 0.00000 0.002 0.00000 0.1 0.00000 1 0.00000 Percent Total: 0% 0.0000

0.06 bbls

0.23 bbls

JOINT INVESTIGATION REPORT FOR INCIDENTING: 180002 JIV report S/N: 0522

23. GENERAL STATUS OF THE SITE

Α.	Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

24. REPRESENTATIVES

OURCES DPR : D PR AND NPF NOMINATED REPRESENTATIVES WERE AND RESPONSE Agency [NOSDRA]: D UNABLE TO ATTEND JIV DUE TO
ources DPR : REPRESENTATIVES WERE ad Response Agency [NOSDRA]: UNABLE TO ATTEND JIV DUE TO
ATTEND JIV bue To
ATTEND JIV DUE TO
NUN-POSSESS ON OF
REQUIRED CERTIFICATION
Company [SPDC]: FOR FLIGHT OPERATIONS TO SITE
findings: 🗖
led out with same findings□
1
•

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 180002 JIV report S/N: 0522

25. Appendix 1: Overview sketch of the site

