



Overview: Part of spill impact on Otumara Well22L Flowline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 19<sup>th</sup> May 2014.



Close-up: Bubbling from pinhole on Otumara Well22L Flowline at Ugboegungun. Picture was taken during Joint Investigation of 19<sup>th</sup> May 2014.