JOINT INVESTIGATION REPORT FOR IN	CIDENT NO: 1263 (91 JIV report S/N: 00	721
(Note: As practicable as possible the JIT 1	report is to be signed in the	field by all the participating partie	s)
A. GENERAL INFORMATION:			
1. Spill incident Number: 263	691 2.Type	of incident" OIL SPILL	<u>-</u>
3. Name of Location OKORD	IA MANIE	OLD	_
1KARA 4. Name of nearest community OKD	AMA - R DIA 5. State: RAY	ELSA 6. LGA YENA	Gna
7. Type of Production facility/Installation	<u>*</u>		- •
B. INCIDENT INFORMATION:	•		
	STH OCTO OCTOBER O14 Actual inve		•
☐Firmed soil	Loose soil	Recently excavated area	
Under water	Swampy	Exposed pipe surface	
■ Well Platform (on Water)	•	Drill Rig	
Additional observations around the space of the pressure point within the fence were observed on as at time of invest.	VALVE ON THE D OKORDIA N THE 14" PIPE	۱۹۳ EXPOSED PIPE ۱ ANIFOLD. CRUDE	LINE OIL STAINS FOF LEAK)
POINT VALVE FLANGE e. Description of leak point (tick as	ES WERE OBSE	WED LOOSE (THAT	IS TAMPERED
Description of leak point (uck as	Hack saw cut	T/	BY MUKNOWM
Complete Rupture	□Inward dent,	DWell hard tampaging	ERSON(S)
Failed Weld-on illegal hot tap va		Missing Pipeline/Flowline	NHEN THE JOINT _
Crude oil theft (illegal bunker	•	☐Third party tampering with C	Clamp INVECTI GATIO
Third party tampering with va	lve setting,	☐Third party tampering with f	lange, TEAM
Corrosión	Saver-pit over flow,	☐Surge vessel overflow,	ATTEMPTED
Bulging Outward	☐Flare System/Bund v	rall failure □Accidental 3 rd part	y equipment To
impact 🔲 Valve Failu	ге 🗆 сог	n unit failure Cold vent	TIGHTEN
Relief valve failure	Others (specify)		WITH A
f. Incident caused by:		Con	SPANNER
Third party interference (Sabotag	re Z : crude theft□: Line the	ft□; Accidental 3 rd party damage[IMPACTED IS
Operational Others	(including Mystery spills)_		LTY CLAY,

^{*}This can be: a) Oil Spill b) Drilling fluid/Chemical c) Siltation d) construction e) Encroachment f) Fire,

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721
g. Spill point coordinates Measuring unit (M) Minna Mid bell
Northing: Easting:
127890.32 443595.96
100:
C. RISK ASSESSMENT
10. Type of environment:
Land □Swamp □Water □Seasonal swamp□Shoreline/Waterfront
i. Type of environment to which oil has spread:
Land Swamp
☐Rain ☐Sunny ☐Dry ☐Wet ☐Windy ☐Hot ☐cool 11. Distance from the nearest sensitive habitat
Government reserved and designated protected area [,m] Drinking water source [,m] Built up area [,m] Farmlands [,m] CASSAVA FARMLAND Fish Farm/Pond [,m] IMPACTED BY SPILL. Others (specify).
12. Containment measures put in place;
Booms Trench Dyke Natural depression Pit None Others: CELLOPHANE
13. Any pictures or video coverage? [XV [N]
14. Further response/repair initiated as at the time of JIV? [Y [N]
If yes to item 14, give brief description: THE NUTS ON THE I" PRESSURE POINT VALVE FLANGES WERE
PROPERLY TIGHTENED BY JOINT INVESTIGATION TEAM PERSONNEL ON SECOND DAY OF JOINT INVESTIGATION VISIT. 15. Was there any disruption to the investigation? [Y] [N]
If yes to item 15 give brief description: THE COMMUNITY REPRESENTATIVES AID NOT CONCUR WITH THE
ESTABLISHED SPILL CAUSE OF SABOTAGE DURING BOTH DAYS OF JOINT INVESTIGATION VISITS WHICH NECESSITATED A FURTHER ENGAGEMENT BY SPDC WITH GOVERNMENT REGULATORS AND COMMUNITY REPRESENTATIVES 2018 ON 13TH OCTOBER 2014 AT

WHICH POINT, TECHNICAL CLARIFICATIONS WERE MADE AND ALL JIV PARTIES AGREED ON THE SPILL CAUSE AND SIGNED-OFF THE

JIV REPORT.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721

D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL

SN Type of Structures Description Size Number Comments 17. Crops/Economic Trees S/N Type of crops Young Medium Matured Quantity Comments L CASSAVA MITHIN AND MITHIN AREA OF MITHIN AND MITHIN AREA OF DRILL 2. PALM TREES MITHIN AND REGION 18. Fish/Nets/Ponds Description 19. Phice's (Specify) i.e. Animal Traps S/N Psh/Nets/Ponds Description Quantity/Size Comments 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE 19. Phice's (Specify) i.e. Animal Traps Discription Quantity/Size Comments AREA OF MACTE AREA OF MACTED AREA OF MAC		16. Structures /	Properties						
S/N Type of crops Voung L. CACS AVA L. CACS AVA L. CACS AVA L. CACS AVA WITHIN AN MITHIN AN MITHIN AREA OF SPRIL- 2. PALM TEES 18. Fish/Nets/Ponds S/N Fish/Nets/Ponds Description Quantity/Size Comments 19. Aners (Specify) i.e. Animal Traps Dihers Description Quantity/Size Comments AREA OF MPACT 19. Aners (Specify) i.e. Animal Traps Dihers Description Quantity/Size Comments AREA OF MPACT 19. Aners (Specify) i.e. Animal Traps AREA OF MPACT PRESSURE POINT VALVE FLANGE OBSERVED TO HAVE PRESSURE POINT VALVE FLANGE BEEN NOWN BY UNK NOWN BY	S/N	Type of Stre	tctures	Description	Size	Number		Comments	
S/N Type of crops Voung L. CACS AVA L. CACS AVA L. CACS AVA L. CACS AVA WITHIN AN MITHIN AN MITHIN AREA OF SPRIL- 2. PALM TEES 18. Fish/Nets/Ponds S/N Fish/Nets/Ponds Description Quantity/Size Comments 19. Aners (Specify) i.e. Animal Traps Dihers Description Quantity/Size Comments AREA OF MPACT 19. Aners (Specify) i.e. Animal Traps Dihers Description Quantity/Size Comments AREA OF MPACT 19. Aners (Specify) i.e. Animal Traps AREA OF MPACT PRESSURE POINT VALVE FLANGE OBSERVED TO HAVE PRESSURE POINT VALVE FLANGE BEEN NOWN BY UNK NOWN BY		ONI		MIT	IN	AREA	0F	TMPA	<u>c</u> T
L CASS AVA WITHIN AN WITHIN AREA OF SPILL 250 M² IMPACTED WITHIN AN REGION		17. Crops/Econ	omic Trees	1 <u></u>			j		
2. PALM REES 2. DIMPACED 18. Fish/Nets/Ponds Description Quantity/Size Comments 19. Theres (Specify) i.e. Animal Traps 19. Theres (Specify) i.e. Animal Traps 19. There (Specify) i.e. Anima	S/N		Young			Matured			
2. PALM TRES 18. Fish/Nets/Ponds Description 19. Iners (Specify) i.e. Animal Traps Dithers Description Quantity/Size Comments 19. Iners (Specify) i.e. Animal Traps Dithers Description Quantity/Size Comments PREAD OF MPACT 19. Iners (Specify) i.e. Animal Traps Dithers Description Quantity/Size Comments PREAD OF MPACT Cast Philo-Description OF Leak Point (while detail report of the leak point should be contained in the leak point should be added as an appendix 1) PRESSURE PO INT VALUE PRESSURE PO INT VALUE BEEN NOWN BY UNKNOWN BY UNKNOWN BY UNKNOWN PRESSON(S)		CFI33 AVA			V		3		THIN.
S/N Fish/Nets/Ponds Description Quantity/Size Comments 19. Ahers (Specify) i.e. Animal Traps 1	2.	PALM TRE	ES						
SN Fish/Nets/Ponds Description Quantity/Size Comments 19. Iners (Specify) i.e. Animal Traps St. Dihers Description Quantity/Size Comments Quantity/Size Comments PREAD OF MPACT Comments OF MPACT Description Quantity/Size Comments PREAD OF MPACT Comments PREAD OF MPACT PRESSURE POINT (while detail report of the leak point should be contained in the land size, overview sketch of the site should be added as an appendix 1) PRESSURE POINT (ALVE TO MAN PERED WITH AVE TO MAN PERSON(S) PERSON(S) PERSON(S) PRESSURE (BEEN NOWN)		18. Fish/Nets/Po	onds				APPR	OXIMATEL	- Y
19 Iners (Specify) i.e. Animal Traps Standard Dithers Description Quantity/Size Comments	S/N	Fish/Nets/Por	ds D	escription		Quantity/Size			
19 Iners (Specify) i.e. Animal Traps Standard Dithers Description Quantity/Size Comments			ON	E Wi	ŢĦıĸ	AREA	OF	IMPA	cT
RE OBSERVED NUTS OBSERVED NUTS OBSERVED NUTS TAMPERED NUTS PRESSURE POINT VALUE OBSERVED NUTS BEEN NOWN BY UNKNOWN BY UNKNOWN PERSON(S) PERSON(S) PERSON(S) PERSON(S)	14	19. Thers (Spe	cify) i.e. Ar	imal Traps					
PRESSURE POINT VALVE OBSERVED TO HAVE OBSERVED WITH BY UNKNOWN BY UNKNOWN PERSON(S) PERSON(S) THAT IS, THAT IS,		Others	D	escription		Quantity/Size	Commen	ts	
PRESSURE POINT VALVE OBSERVED TO HAVE OBSERVED WITH BY UNKNOWN BY UNKNOWN PERSON(S) PERSON(S) THAT IS, THAT IS,		Ma	11-	141.		10-1	VE	LADA	ΛŢ
PRESSURE POINT VALVE OBSERVED TO HAVE OBSERVED WITH BY UNKNOWN BY UNKNOWN PERSON(S) PERSON(S) THAT IS, THAT IS,	ge \	ا الم	NE	\\ 	HIN	HKFU	01	HIMI	C I
PRESSURE POINT VALVE OBSERVED TO HAVE OBSERVED WITH BY UNKNOWN BY UNKNOWN PERSON(S) PERSON(S) THAT IS, THAT IS,	E	PHIC DESC	RIPTION sketch of th	OF LEAK POI e site should be	NT (while de added as an a	tail report of the . ppendix 1)	leak point si	hoi.ld be conta	ined in the
PERSON(S) PERSON(S) THAT IS, THAT IS,	X	6/				l"			
PERSON(S) PERSON(S) THAT IS, THAT IS,	· E					PRESSURE		The same of the sa	-
PERSON(S) PERSON(S) THAT IS, THAT IS,		3				VALVE	.\\	1110	~
BEENKNOWN BY UNKNOWN PERSON(S) (THAT IS)	E	=		LANGE	NUTS A	IE .			WES
BEENKNOWN BY UNKNOWN PERSON(S) (THAT IS)	RE		08	SERVED	REDW	1TH-		- In	ANG
PERSON(S) (THAT IS)		(6)	BEET	MUCLINE		1	O	N. S.	-
(THAT IS)	E	-111	KA w				1		
TION OF DIA POINT ON TONO POINT ON POINT ON PRESSURE POINT ON PIPELINE TO RISER.	TA.	lbte	\	THAT IS	S.	1	Ĺ	EAK	
CTION OF DIA MANIFOLD TO POST TION OF SHOWING POINT ON TO PRESSURE POINT ON PIPELINE TO RISER.			1	POSENE		4	•	POINI	
CTION OF DIA ME POINT ON TO RISER. O AMA OR PERSON POINT ON PIPELINE TO RISER.					NIFOL) n'			
TION OF PIARE POINT ON PIPELINE TO RISER).	TION	HI	~ ^1	IA MA	POSITION	3			
TION OF DIA RE POINT ON NE POINT ON PIPELINE TO RISER!	-	NU	Drok i	W. Daino	Hage 3 of	8 <u>=</u>			
DAMA OKUSSURY POW PIPELE TO K	10	N OFD	IADE	POINT OF	HINE	RISER).			
	MAGO	-OKES	TAK	POLIT PIPE	SE TO	T			

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721

1	Northing (M)	Easting (M)
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
		- JX
	· · · · · · · · · · · · · · · · · · ·	<u> </u>
		X.S
		A.
_		A CONTRACTOR OF THE CONTRACTOR
		<u> </u>
	· · · · · · · · · · · · · · · · · · ·	
	<u> </u>	
		1 o
	· · · · · · · · · · · · · · · · · · ·	
		
	<u> </u>	X
		(7 Y
		7 1/21/1
		0, 19, 13
_		-0/
) 60
	-	

							1	
			VOSDIA BAABII	FOLD SBILL	@ IKVBVI	L	<u> </u>	
			KORDIA MANI	POLD SPILL	@ IKANAH			
MINN	A MIL		NODTHINGS			<u> </u>		
PTS		EASTINGS	NORTHINGS	}				
L—	819	443602.19		+			<u>-</u>	
	820	443633.07					 	-
<u> </u>	821	443639.25				 	 	
<u> </u>	822	443700.85				<u> </u>	 	
	823	443716.19					 	
<u> </u>	824	443709.99				 	 	├ ───
	830	443564.94				 	 	
	831	443580.4				 		
	832	443602.05	127868,79			 	ļ	
	833	443562.12	127908.86			 	 _	
	834	443552.91	127918.11				 	
	835	443516.09	127964.33			<u> </u>	↓	
	836	443500.64	127952.08					
	837	443510.02	127995.08					
	838	443540.79	127982.68			<u> </u>		├
	839	443537.66	127967.33				<u> </u>	ļ
	842	443577.67	127951.84					<u> </u>
	843	443589.99	127951.8					<u> </u>
	844							
	845	443605.4	127951.75					
	846		-					
\vdash	847	 	+ -					
-	848	+		+				
-	849							
-	853							
 	85 ⁴					1		
<u> </u>	85			+	 			
-	85	+				 		
1-						 		
-	85				 		_	
<u> </u>	85				 			
	85			+	 	<u> </u>		
-	86				<u> </u>	+ -		
<u> </u>	86			+	+-	 		
<u> </u>	86				 		_	
ļ	86				+	+	+	
\vdash	86				+ -	+	- 	
<u> </u>	86					- -		
<u> </u>	86				 	 	+	
<u> </u>	86				 		- 	_
<u> </u>	86				 			-
	86				 			-
	836	443416.2	25 127964.8	3				


8361	443301.5	127980.62			
8690	443304.65	128037.47			
8660	443029.89	127480.56			Ţ
8650	442987.78	127520.57			
8300	443487.69	127776.34			
8301	443376.56	127705.7			
			i i		

•

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721

G.	INCID	ENT	INFO	RMA	TION:

Total calculated are	a of impact 7./DHA		
Impact within SPD0	c'r.o.w \es		
 Impact outside SPD 	CRO.W YES		
21. Volume of oil recovered bef	ore completion of JIV (V _{recJ}):	: .	
(1) · · · · · · · · · · · · · · · · · · ·	Recovered oil V _{reed} :	NIL	Barrels
Controlled recovery/evacuation	n from source with no impac	t to environment:	•
	Rarrels Barrels		



*Notes:

Volume estimation was done using an excel based tool (see attached for details on the calculation)

Reported spilled volume is an estimate

Write other relevant notes taken into consideration for estimating the spilled in the box below:

IN ADHERENCE TO THE WORK INSTRUCTIONS FOR JOINT-INVESTIGATION OF OIL SPILL INCIDENTS (JIV) PROCEDURE) WHICH REQUIRES DEDUCTION OF YET-TO-BE-RECOVERED SPILL VOLUMES IN SITUATIONS WHERE A NEW SPILL IS SUPERIMPOSED ON AN EXISTING SPILL, THE UNRECOVERED SPILL VOLUME ESTIMATE OF 20 BARRELS WAS DEDUCTED TO ARRIVE AT THE ESTIMATED REPORTED VOLUME ABOVE. APPROXIMATELY 96% RECOVERY WAS MADE OF THE PREVIOUS INCIDENT(ID 1194704) BEFORE THE PRESENT SPILL OCCURRED.

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of m¹ to barrels is Volume (m3) x 6.29; **Round up estimated volume to next whole number using the following rules:

• Any spill volume in excess of 1 bbl is rounded up to the next whole number.

Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ------ Reported volume = 16 bbl | Calculated volume = 0.35 bbl | Reported volume = 0.4 bbl | Calculated volume = 0.01 bbl | Reported volume = 0.1 bbl | Reporte

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

ESTIMATION OF OIL SPILL VOLUME

)/L S	SPILLED ONSHORE	OFFSHORE (Leak stopped a	t source)		·
прас	ted Area Details		•		
7	otal Calculated Area of	Impact			71,009.00 m²
i Ir	mpact within SPDC R.O.V	v ·			m²
	mpact outside SPDC R.O		•	•	m²
	.,,	•••			
olum	e of oil recovered befor	e completion of JIV (V)			
	stimated Recovered oil (0.00 bbis
	(1	10.7			0.00
Œ	stimated Recovered oil	(Net) V _{resi}			0.00 bbls
-			,		
omb	utation of estimated res	Idual volume on site			
		of free phase oil (on land or confined	l umter hackel		
	otal area occupied by por	- •	water body/		54,150.00 m ²
	werage depth of pool of fi	•			-
					0.003 m
E	mulsification factor	(If applicable, else 0%)			0%
_					
		of free phase oil, V _{pool}			162.45 m ³
£	stimated Volume of por	ol of free phase oil, V _{poel}			1,021.81 bbis
C	Computation of estimate	d volume of inflitrated oil in the soil	(V int)		
1 V	olume of infiltrated oil a	t spill point (V _{ints})			
i T	otal area covered by the	oil (infiltration)			m²
		n above leaking facility i.e. pipeline/flov	viine		m
	Soil type				- Select -
	effective porosity of the	(lioa e			0%
••		•			
u C	anaa of enill				
* 0	Cause of spill				Third party interference
۔.	Coloulation of doubles	5.28 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -		1	
vi		infiltration below the leaking point on p	<u> </u>		
⊢	Incident Date	JIV Date	Days on Site		
⊢	10/5/2014 10:00	10/9/2014 16:05	4		
- 1	If 'cause of spill' is open	ational, use 1 week as worst case here 'days on site' exceeds 7.	7		
_	SCALIBINI BYCSDI AL	Here days on site exceeds 7.			
Г		Infiltration of oil types in various soil I	unae ve tima		¬
<u> </u>	Soil type	Approximate time to reach		net level	┪
<u> </u>					┥
-	il type	Sand	Loam	Clay	4
_	lonny Medium	3 weeks	3 years	> 10 years	4
В	onny Light	2 days	2 months	> 10 years	」
	il type				Bonny Medium 🔻
/ili A	verage depth of infiltration	n below leaking facility i.e. pipeline/flow	line		0.000 m
ix To	otal depth below ground :	surface of infiltration of oil			0.000m
					
E	stimated Volume of Infi	trated oil. V			0.00 m²
	stimated Volume of Infi		•••		0.00 bbis
2 V	olume of infiltrated oil a	t second spill point [if applicable] (v	71		
	otal area covered by the		स्त्र ()		m²
		n (minuauon) 1 above leaking facility i.e. pipeline/flow	.i:		
	oil type	above scaling racing i.e. pipelinemov	riirie		<u> m</u>
_	, (effective porosity of the	enil			- Select -
W P	e (oneone porosity of the	aun)			0%
v A	verage depth of infiltration	n below leaking facility i.e. pipeline/flow	line		0.000 m
vi To	otal depth below ground s	surface of infiltration of oil			0.000 m
	stimuted Volume of infl				0.00 m ³
			_		
E	stimated Volume of infi	trated oil, V 🛶 .			0.00 bbis

JOINT INVESTIGATION REPORT SPILL VOLUME ESTIMATE FOR INCIDENT NO: 1263691

E-factor Estimated Volume of eve		_		182.93 bbls
C fanta-				15 %
	nor erappación			1,036.62 bbls
Was <i>oil recovery before Ji\</i> Estimated volume available	/ completion done before JIV date?			1 036 62 hbbs
Idina all annual to de la company	A second the second sec			
	> 7 days	40%	25%	
	1-7 days	25%	15%	
 _	< 1 day	Bonny Light 10%	Bonny Medium 5%	
Residence time	of spilled oil (days on site)	Oil ty		
	Evaporation Factors (E-Factor) for S	PDC Crude oil		1
liation of evaporated volu	ıme			
Estimated Volume of oil o				0.00 bbls
Estimated Volume of oil o	on open water. V			0.00 m³
	Percent Total:	0%	0.0000	
Emulsion (30% Oif)	11		0.0000	
Black oil	0.002		0.0000 0.0000	
Dull Dark	0.001		0.0000	
Bright Color	0.0003		0.0000	
Slight Color	0.00015		0.0000	
Silvery	0.00008		0.0000	
Barely Visible	0.00004		0.0000	
	Thickness (mm)	(%)	Volume (m3)	
Spill Factors from USCG FOG	(2000 Edition)	Aid Percentage coverage	<u> </u>	1
		Link to Coverage Visual		
	oil on water based on coloration			<u> </u>
Total area of oil on open w	•			m ²
Computation of volume a	of oil on open water based on standa	ord coloration		
Estimated Total Volume	of implificated cit, V _M			14.81 bbls
Estimated Total Volume				2.36 m ³
Estimated Volume of Infi	· · · · · · · · · · · · · · · · · · ·	<u> </u>		0.00 bbls
Estimated Volume of Infli	Itrateil oil, V _{Md}			0.00 m³
Average depth below groun	nd surface of infiltration of oil			0. 001 m
			,	
Total Area covered by the cool of for	oit (inflitration) se phase oil in touch with soil			m² m²
	outside immediate spill point(s) regio	on (superficial Impac	t, V _{infd})	2
" 				
Estimated Volume of infil			_	14.81 bbls
Estimated Volume of infil	itrated oil, V			2.36 m ³
Average depth below grous	nd surface of infiltration of oil	•	•	0.001 m
P _a (effective porosity of the	soil)			12 %
Soil type				Silty or sandy day
Total Area of the pool of fre	ee phase oil in touch with soil			1,050.00 m ²
	oil (infiltration)			16,859.00lm²

NOTE: The present spill incident was overlapped by the immediate past spill incident at same location (ID 1194724) where out of an estimated spill volume of 629 barrels, 548 barrels was recovered while some spill was consumed by fire. The unrecovered spill volume estimate of 20 barrels is hereby deducted from the net cumulative estimate of 1,219.56 barrels to arrive at the actual net spill volume eatimate for the present incident; thus, 1,219.56 - 20 = 1,199.56 barrels.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721

23. GENERAL STATUS OF THE SITE

A.	. Joint investigation of the incident site found that there is no residual impact after the initial response and JIT therefore recommend that the site be closed out
В.	Investigation of the incident site showed that there is residual impact on site requiring further works

24. REPRESENTATIVES

This report was filled, agreed a	nd signed by the following	g Joint investigation represent	atives:
	•		

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spiil Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Patroieum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

Tick as applicable

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1263691 JIV report S/N: 00721

25. Appendix 1: Overview sketch of the site

